



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	CR-V I-DTEC SE PLUS
Colour	Black
Year of manufacture	2016
Top speed	122 mph
0 - 60 mph	10.0 seconds
Gearbox	9 speed automatic

Engine & fuel consumption

Power	158 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 3

Date	2023-08-12
Pictures	23
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

Date	2021-05-26
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 1

Date	2021-05-23
Pictures	0
Listing price	View report

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-12
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	15
Total items failed	2

MOT #8	2023-10-13 10:34
MOT test number	720769479728
Result	✓ Passed
Next expiry date	2024-10-12

MOT #7	2023-02-28 13:53
MOT test number	913905548815
Result	✓ Passed

MOT #6	2022-03-08 12:16
MOT test number	978093230012
Result	✓ Passed

MOT #5	2021-06-08 14:32
MOT test number	630279951752
Result	✓ Passed

**MOT #4** 2020-06-04 07:51**MOT test number** 878898154064**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Under trays fitted**MOT #3** 2020-06-03 13:35**MOT test number** 978869682227**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Under trays fitted**Minor** Offside Windscreen wiper blade defective Split on the ends (3.4 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2019-06-11 15:07**MOT test number** 832133714132**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Items removed from driver's view prior to test**Advice** Under trays fitted



MOT #12019-06-11 09:19

MOT test number538707761327

Result

Failed

Fail

Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice

Under trays fitted

Advice

Nearside Rear Nail in tyre

Advice

Items removed from driver's view prior to test

Advice

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Offside Rear Nail in tyre



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
12 October 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	12 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-06-30
Last registration	2023-10-13
Complete history	See info



Registration #1	2016-06-30	26 mi
Registration #2	2019-06-11	24.094 mi
Registration #3	2019-06-11	24.094 mi
Registration #4	2020-06-03	30.048 mi
Registration #5	2020-06-04	30.048 mi
Registration #6	2020-06-04	30.048 mi
Registration #7	2020-06-04	30.048 mi
Registration #8	2020-06-04	30.048 mi
Registration #9	2020-06-04	30.048 mi
Registration #10	2020-06-04	30.048 mi
Registration #11	2020-06-04	30.048 mi
Registration #12	2020-06-04	30.048 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	74%
Pedestrian	68%
Safety systems	66%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1685 mm
Length	4605 mm
Wheel base	2630 mm
Kerb weight	1724 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	N16A42003105