



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D2 SE LUX
Colour	White
Year of manufacture	2015
Top speed	121 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	103 g/km
CO2 label	B






Internet history

Entry 2


Date	2021-12-26
Pictures	28
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-12-22
Pictures	27
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-19
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	20
Total items failed	2

MOT #9	2024-04-17 09:45
MOT test number	855042052807
Result	✓ Passed
Next expiry date	2025-04-19
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Tyre slightly damaged/cracking or perishing both tyres (5.2.3 (d) (ii))

MOT #8	2023-04-11 10:36
MOT test number	259575573808
Result	✓ Passed
Advice	Rear Coil spring worn Both sides (5.3.1 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

MOT #7	2022-04-12 14:34
MOT test number	902027461863
Result	✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #6**

2022-04-12 12:44

**MOT test number**

342360671772

**Result****✗ Failed****Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MAJOR** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #5**

2021-04-20 10:48

**MOT test number**

660254011438

**Result****✓ Passed****Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #4**

2020-04-10 13:26

**MOT test number**

964888120521

**Result****✓ Passed****Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #3** 2020-04-10 13:26**MOT test number** 363046930349**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #2** 2019-03-29 17:03**MOT test number** 591569113659**Result** ✓ Passed**MOT #1** 2018-03-29 14:17**MOT test number** 380393037491**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
19 April 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	19 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>RK15FFB</b>
Plate since	2019-03-29
Current registration	<b>RK15FFB</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-23
Last registration	2024-04-17
Complete history	<a href="#">See info</a>



Registration #1	2015-03-23	19 mi
Registration #2	2018-03-29	32.016 mi
Registration #3	2019-03-29	39.809 mi
Registration #4	2020-04-10	48.433 mi
Registration #5	2020-04-10	48.433 mi
Registration #6	2021-04-20	54.885 mi
Registration #7	2022-05-20	55.277 mi
Registration #8	2023-05-20	55.277 mi
Registration #9	2023-05-20	55.277 mi
Registration #10	2023-05-20	55.277 mi
Registration #11	2023-05-20	55.277 mi
Registration #12	2024-04-17	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2715 mm
Kerb weight	1544 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	4171507