





report date: 2024-03-28

## General information

Make	LAND ROVER
Model	FREELANDER TD4 XS
Colour	Silver
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	11.7 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	110 kW / 150 HP / 150 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

### Entry 1

Date	2021-06-10
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-09-01
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	21
Total items failed	0

MOT #10	2023-08-24 07:28
MOT test number	278340438380
Result	<b>✓</b> Passed
Next expiry date	2024-09-01

MOT #9	2022-08-26 10:57
MOT test number	801963745632
Result	<b>√</b> Passed

MOT #8	2021-09-02 11:32
MOT test number	136550363053
Result	<b>✓</b> Passed

MOT #7		2021-09-01 15:24
MOT test	number	867721063141
Result		<b>X</b> Failed
MAJOR	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #6	2020-10-06 07:36
MOT test number	975632287881
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5 2019-10-24 10:12 **MOT** test number 950968872961 Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Advice Rear Child Seat fitted not allowing full inspection of adult belt Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e)) Advice Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4		2019-10-24 07:44
MOT test	number	599519950916
Result		<b>×</b> Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
DANGER	OUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))	
Advice	Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

885942234443

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2

MOT test number

287805568726

Result

Advice Nearside Front tyres near limit

Advice Offside Rear tyre near limit

MOT #1	2016-12-10 13:37
MOT test number	593908978837
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

## Tax & MOT check





Expires: 1 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	1 September 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1


Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download to	
***************************************	
	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-12-13
Last registration	2023-08-24
Complete history	See info



Registration #1	2013-12-13	6 mi
Registration #2	2016-12-10	44.497 mi
Registration #3	2017-12-08	53.431 mi
Registration #4	2018-10-30	60.313 mi
Registration #5	2019-10-24	70.887 mi
Registration #6	2019-10-24	70.888 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2005 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1735 kg
Max. allowed weight	2505 kg

## Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ794052205224DT

CarCheck.co.uk page 12/12