



report date: 2024-03-28

General information

Make	BMW
Model	525 525D SE
Colour	Silver
Year of manufacture	2004
Top speed	143 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	177 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	6
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-05
Pictures	6
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-05
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	39
Total items failed	11

MOT #22	2023-05-06 10:20
MOT test number	650012867230
Result	✓ Passed
Next expiry date	2024-05-05
Advice	Front undertray fitted obstructing the inspection of testable items
Advice	Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))

MOT #21	2023-05-02 13:11
MOT test number	295204026738
Result	✗ Failed
Fail	Front Registration plate inscription illegible (0.1 (b))
Advice	Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))
Fail	Front Brake disc in such a condition that it is seriously weakened both side (1.1.14 (a) (ii))
Advice	Front undertray fitted obstructing the inspection of testable items

MOT #20	2022-04-01 09:50
MOT test number	470747779660
Result	✓ Passed
Advice	Undertray fitted obstructing the inspection of testable items
Advice	Front Brake disc worn, but not excessively offside and nearside (1.1.14 (a) (ii))

**MOT #19** 2021-04-21 12:33**MOT test number** 357792352278**Result** ✓ Passed**MOT #18** 2021-04-20 10:37**MOT test number** 591412782018**Result** ✗ Failed**Fail** Headlamp aim not tested both side (4.1.2 (b))**Fail** Front Headlamp has a product on the lens so that the light output is severely reduced both side (4.1.4 (b))**MOT #17** 2019-07-20 09:41**MOT test number** 725988647026**Result** ✓ Passed**MOT #16** 2017-12-20 16:51**MOT test number** 506690176260**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Inner Suspension arm has slight play in a pin/bearing (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Oil leak**Advice** Offside Rear Inner Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #15** 2017-12-16 12:06**MOT test number** 372077546313**Result** ✗ Failed**Advice** Nearside Rear Inner Suspension arm has slight play in a pin/bearing (2.4.G.2)**Advice** Oil leak**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Lower Suspension arm has excessive play in a ball joint which goes through suspension arm and hub (2.4.G.2)**Advice** Offside Rear Inner Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #14** 2016-11-17 14:39**MOT test number** 864623980916**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #13** 2015-11-26 12:27**MOT test number** 345885276862**Result** ✓ Passed

**MOT #12**

2014-11-20 14:42

MOT test number

535134824319

Result

✓ Passed

Advice Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Notice Under-trays fitted obscuring some underside components

Notice Oil leak

Advice Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Child seat fitted not allowing full inspection of adult belt

Advice Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Notice Engine covers fitted obscuring some components in the engine bay

MOT #11

2014-11-19 10:34

MOT test number

409483724357

Result

✗ Failed

Fail Nearside Rear Rear position lamp(s) not working (1.1.A.3b)

Advice Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Under-trays fitted obscuring some underside components

Advice Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Notice Oil leak

Fail Nearside Rear Suspension arm has excessive play in a pin/bush (2.4.G.2)

Notice Child seat fitted not allowing full inspection of adult belt

Advice Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Notice Engine covers fitted obscuring some components in the engine bay

**MOT #10** 2013-05-31 17:21**MOT test number** 215001653469**Result** ✓ Passed**MOT #9** 2013-05-16 15:43**MOT test number** 815756233178**Result** ✗ Failed**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #8** 2012-05-18 15:32**MOT test number** 299709032481**Result** ✓ Passed**Notice** Rear brake pads wearing low**MOT #7** 2012-05-17 10:01**MOT test number** 376858132186**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** Rear brake pads wearing low**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2010-11-26 08:59**MOT test number** 441150830477**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front discs worn

**MOT #5** 2009-11-27 15:25**MOT test number** 432801439361**Result** ✓ Passed**MOT #4** 2009-11-24 15:20**MOT test number** 810188029317**Result** ✗ Failed**Fail** Nearside Rear Road wheel cracked (4.2.A.1a)**Fail** Nearside Front Road wheel cracked (4.2.A.1a)**MOT #3** 2008-11-27 09:00**MOT test number** 434032338330**Result** ✓ Passed**Notice** Both front tyres weearing on inner edges**MOT #2** 2008-05-07 13:17**MOT test number** 732348728156**Result** ✓ Passed**Notice** Nail in offside rear tyre**MOT #1** 2007-11-28 11:24**MOT test number** 774162237373**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
5 May 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	5 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-12-10
Last registration	2023-05-06
Complete history	See info



Registration #1	2004-12-10	6 mi
Registration #2	2007-11-28	39.894 mi
Registration #3	2008-05-07	46.249 mi
Registration #4	2008-11-27	52.875 mi
Registration #5	2009-11-24	64.727 mi
Registration #6	2009-11-27	64.727 mi
Registration #7	2010-11-26	77.824 mi
Registration #8	2012-05-17	87.196 mi
Registration #9	2012-05-18	87.196 mi
Registration #10	2013-05-16	93.843 mi
Registration #11	2013-05-31	93.851 mi
Registration #12	2014-11-19	99.302 mi
Registration #13	2015-05-20	105.753 mi
Registration #14	2015-05-20	105.753 mi
Registration #15	2015-05-20	105.753 mi
Registration #16	2015-05-20	105.753 mi
Registration #17	2015-05-20	105.753 mi
Registration #18	2015-05-20	105.753 mi
Registration #19	2015-05-20	105.753 mi
Registration #20	2015-05-20	105.753 mi
Registration #21	2015-05-20	105.753 mi
Registration #22	2015-05-20	105.753 mi
Registration #23	2015-05-20	105.753 mi
Registration #24	2015-05-20	105.753 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1846 mm
Height	1469 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1660 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Engine number	33485614