



CP67CDU


report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TIGUAN SEL TDI BLUEMOTION TECHNOLOGY
Colour	Grey
Year of manufacture	2017
Top speed	125 mph
0 - 100 km/h	9.3 seconds
0 - 60 mph	9.3 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	57.6 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 2



Date	2022-01-09
Pictures	30
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-09-16
Pictures	29
Listing price	<a href="#">View report</a>



source: [yesauto.com](https://www.yesauto.com)



MOT history

MOT expiry date	2024-06-09
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #5	2023-06-10 11:29
MOT test number	485014995333
Result	✓ Passed
Next expiry date	2024-06-09

MOT #4	2022-09-01 10:00
MOT test number	383465728226
Result	✓ Passed
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3	2021-09-10 09:47
MOT test number	976820795997
Result	✓ Passed

**MOT #2** 2020-11-28 11:17**MOT test number** 103897970215**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.7mm (5.2.3 (e))

**MOT #1** 2020-11-28 11:17**MOT test number** 956320300213**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.7mm (5.2.3 (e))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
9 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	9 June 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-11-30
Last registration	2023-06-10
Complete history	<a href="#">See info</a>



Registration #1	2017-11-30	14 mi
Registration #2	2020-11-28	23.403 mi
Registration #3	2020-11-28	23.403 mi
Registration #4	2021-09-10	28.673 mi
Registration #5	2023-06-10	28.673 mi
Registration #6	2023-06-10	28.673 mi
Registration #7	2023-06-10	28.673 mi
Registration #8	2023-06-10	28.673 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	84%
Pedestrian	72%
Safety systems	68%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2099 mm
Height	1654 mm
Length	4486 mm
Wheel base	2677 mm
Kerb weight	1515 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	DFGA215344