



report date: 2024-03-28

General information

Make	KIA
Model	PICANTO VR7
Colour	Red
Year of manufacture	2015
Top speed	95 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	95 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-30
Pictures	21
Listing price	<a href="#">View report</a>



source: yesauto.com





## MOT history

MOT expiry date	2025-02-09
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	11
Total items failed	5

MOT #11	2024-02-06 10:53
MOT test number	958221013269
Result	✓ Passed
Next expiry date	2025-02-09

MOT #10	2023-02-02 11:07
MOT test number	918216141616
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement [rear bush] (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2023-02-02 11:07
MOT test number	679772547934
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement [rear bush] (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2022-01-28 11:02
MOT test number	540297955044
Result	✓ Passed

**MOT #7** 2021-02-10 10:11**MOT test number** 730812815146**Result** ✓ Passed**MOT #6** 2021-02-09 15:59**MOT test number** 925398607977**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**MOT #5** 2020-09-08 10:11**MOT test number** 433291313692**Result** ✓ Passed**Advice** O/s/f bottom arm rear bush starting to detach**Advice** O/s main front to rear brake pipe starting to corrode**MOT #4** 2019-08-16 14:22**MOT test number** 764091185342**Result** ✓ Passed**Advice** Offside Rear Unable to check for wheel bearing roughness due to slightly binding brake**Advice** Nearside Rear unable to check for wheel bearing roughness due to slightly binding brake

**MOT #3** 2019-08-16 14:22**MOT test number** 269185285101**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear Unable to check for wheel bearing roughness due to slightly binding brake**Advice** Nearside Rear unable to check for wheel bearing roughness due to slightly binding brake**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**MOT #2** 2018-08-31 12:23**MOT test number** 344581929384**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2017-09-13 11:06**MOT test number** 289647913894**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
9 February 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	9 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable




Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	NL15JZR
Plate since	2019-09-28
Current registration	NL15JZR
Plate since	2019-09-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-31
Last registration	2024-02-06
Complete history	<a href="#">See info</a>



Registration #1	2015-03-31	23 mi
Registration #2	2017-09-13	12.980 mi
Registration #3	2018-08-31	23.861 mi
Registration #4	2019-08-16	33.609 mi
Registration #5	2019-08-16	33.609 mi
Registration #6	2020-09-08	39.027 mi
Registration #7	2020-09-08	39.027 mi
Registration #8	2020-09-08	39.027 mi
Registration #9	2020-09-08	39.027 mi
Registration #10	2020-09-08	39.027 mi
Registration #11	2020-09-08	39.027 mi
Registration #12	2020-09-08	39.027 mi
Registration #13	2020-09-08	39.027 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	83%
Pedestrian	47%
Safety systems	43%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1595 mm
Height	1480 mm
Length	3595 mm
Wheel base	2370 mm
Kerb weight	1015 kg
Max. allowed weight	1340 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G3LAEP136081