





report date: 2024-03-28

General information

| Make | KIA |
|---------------------|-------------------|
| Model | VENGA 3 |
| Colour | Red |
| Year of manufacture | 2011 |
| Top speed | 110 mph |
| 0 - 60 mph | 11.8 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| Power | 123 BHP |
|-------------------------|---------------------|
| Max. torque | 156 Nm at 4.200 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 31.4 mpg |
| Consumption extra urban | 48.7 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 164 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-06-23


Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-02-21 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 22 |
| Total items failed | 5 |

| MOT #15 | | 2024-02-16 08:59 |
|-----------|---------------------------------------------------------------------------------|------------------|
| MOT test | number | 774834470459 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-02-21 |
| Advice | Nearside Front Suspension arm ball joint has slight play Borderline pass (5.3.4 | (a) (i)) |
| Advice | Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Nearside Side repeater slightly discoloured (4.4.3 (a)) | |
| Advice | Play in steering rack inner joint(s) | |
| Advice | Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Rear Coil spring corroded N/S/R and O/S/R coil springs slightly corroded (5.3.1 | (b) (i)) |

| MOT #14 | | 2023-02-20 09:13 |
|----------------------------------------------------------------------------------|----------------------------------------------------------------------------|------------------|
| MOT test | number | 976612569579 |
| Result | | ✓ Passed |
| Advice | Offside Play in steering rack inner joint(s) | |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

CarCheck.co.uk page 3/13



MOT #13 2023-02-20 09:13

MOT test number 170614346055

Result X Failed

Pass with rectification Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Play in steering rack inner joint(s)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12 2022-02-21 11:34

MOT test number 789443277865

Result
✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Advice Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #11 2021-02-22 13:22

MOT test number 466272389696

Result ✓ Passed

MOT #10 2020-03-03 10:18

MOT test number 790687032127

Result
✓ Passed

MOT #9 2019-03-22 13:25

MOT test number 601940062921

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

CarCheck.co.uk page 4/13



Result

AO11ZZL

report date: 2024-03-28

✓ Passed

MOT #8 2019-03-22 11:09 **MOT** test number 528395037167 Result × Failed Fail Stop lamp(s) all not working (4.3.1 (a) (iii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Electronic stability control warning lamp indicates a fault (7.12 (e)) Fail

 MOT #7
 2018-03-06 10:11

 MOT test number
 310012515543

 Result
 ✓ Passed

 MOT #6
 2017-03-08 11:20

 MOT test number
 765718250380

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

 MOT #5
 2016-03-23 15:32

 MOT test number
 960507759291

 Result
 ✓ Passed

 MOT #4
 2016-03-23 15:32

 MOT test number
 166380165916

 Result
 X Failed

Pass with rectification Offside Front Headlamp aim too low (1.8)

CarCheck.co.uk page 5/13



report date: 2024-03-28

| MOT #3 | 2015-06-18 10:20 | |
|-------------------------|--------------------------------------------------------------------------------------------|--|
| MOT test number | 718269365115 | |
| Result | ✓ Passed | |
| | | |
| MOT #2 | 2014-06-11 10:59 | |
| MOT test number | 477012664102 | |
| Result | ✓ Passed | |
| | | |
| MOT #1 | 2014-06-11 10:59 | |
| MOT test number | 297622164405 | |
| Result | ▼ Failed | |
| Pass with rectification | Pass with rectification Windscreen wiper does not clear the windscreen effectively (8.2.2) | |

CarCheck.co.uk page 6/13



Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 64 |
| MOT expiry date | 21 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-----------------------------------------|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

| Owner | history |
|-------|----------|
| OWITE | THISCOLY |

| o met motory | | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--|
| For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report | | |
| ********* | | |
| *************************************** | | |
| THE STREET STREET | | |
| ********* | | |
| *************************************** | | |
| THE PROPERTY OF THE PROPERTY O | | |
| | More info > | |
| Plate changes | | |
| See in this check if this KIA had different number plates. | | |
| Number of plates | | |
| Current registration | UK NE | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info > | |

CarCheck.co.uk page 10/13



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2011-06-30 |
| Last registration | 2024-02-16 |
| Complete history | See info |



| Registration #1 | 2011-06-30 | 23 mi |
|------------------|------------|-----------|
| Registration #2 | 2014-06-11 | 13.478 mi |
| Registration #3 | 2015-06-18 | 16.758 mi |
| Registration #4 | 2016-03-23 | 19.952 mi |
| Registration #5 | 2016-03-23 | 19.952 mi |
| Registration #6 | 2017-03-08 | 30.919 mi |
| Registration #7 | 2018-03-06 | 41.040 mi |
| Registration #8 | 2019-03-22 | 47.842 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 9.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 9.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 ms |
| Registration #16 | | 10.777 au |

More info >

page 12/13 CarCheck.co.uk



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 85% |
| Pedestrian | 64% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| Width | 1765 mm |
|---------------------|---------|
| Height | 1600 mm |
| Length | 4068 mm |
| Wheel base | 2615 mm |
| Kerb weight | 1269 kg |
| Max. allowed weight | 1730 kg |

Additional information

| Fuel tank capacity | 48 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 13/13 |

Number of axles 2

Engine number G4FCAZ200501