



RENAULT

LTIORLZ


report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC SL27 DCI 115 SWB P/V
Colour	White
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg







Internet history

Entry 1

Date	2022-05-05
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-17
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	30
Total items failed	26

## MOT #19 2024-03-06 10:25

MOT test number 107941431251

Result ✓ Passed

Next expiry date 2025-03-17

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Play in steering rack inner joint(s)

## MOT #18 2023-03-18 10:23

MOT test number 452642470677

Result ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 195/65/16C (5.2.3 (e))

## MOT #17 2022-04-19 11:51

MOT test number 735962338969

Result ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Front to rear pipe. (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material Front to rear pipe. (1.1.11 (c))

**MOT #16**

2022-04-19 11:35

**MOT test number**

731308841496

**Result****✗ Failed**

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material Front to rear pipe. (1.1.11 (c))

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Front to rear pipe. (1.1.11 (c))

**MOT #15**

2021-04-30 11:29

**MOT test number**

245990104637

**Result****✓ Passed****MOT #14**

2021-04-27 09:19

**MOT test number**

715310872745

**Result****✗ Failed**

**Fail** Nearside Rear Brake cable has restricted free movement (1.1.15 (e))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Fail** Power steering pipe/hose modification unsafe insecure (2.1.5 (f) (i))

**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #13**

2020-10-21 09:15

**MOT test number**

224648890896

**Result**

✓ Passed

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Play in steering rack inner joint(s)**MOT #12**

2020-10-21 09:15

**MOT test number**

550324790483

**Result**

✗ Failed

**Pass with rectification** Stop lamp(s) all not working (4.3.1 (a) (iii))**Pass with rectification** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Pass with rectification** Nearside Front Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Play in steering rack inner joint(s)**MOT #11**

2019-10-03 14:13

**MOT test number**

948984799388

**Result**

✓ Passed

**MOT #10**

2018-07-25 09:04

**MOT test number**

662369112132

**Result**

✓ Passed

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front worn on inner edge
- Advice** Offside Rear Nail in tyre
- Advice** N/s front shock absorber wet
- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front worn on inner edge

**MOT #9**

2018-07-25 07:45

**MOT test number**

442786212839

**Result**

✗ Failed

- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front worn on inner edge
- Advice** Offside Rear Nail in tyre
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Fail** Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Front worn on inner edge

**MOT #8** 2017-02-22 12:36**MOT test number** 684778489003**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** All 4 tyres are wearing on the edges.**MOT #7** 2017-02-22 12:36**MOT test number** 767107213439**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** All 4 tyres are wearing on the edges.**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2016-03-01 10:17**MOT test number** 260522654644**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-03-04 14:46**MOT test number** 246923165075**Result** ✓ Passed**MOT #4** 2015-03-04 14:46**MOT test number** 779903465064**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)



MOT #3	2014-02-25 13:38
MOT test number	506076154062
Result	✓ Passed

MOT #2	2014-02-25 13:38
MOT test number	869876554068
Result	✗ Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2013-02-22 14:57
MOT test number	207083753063
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
17 March 2025

<b>Tax status</b>	Valid until 1 March
-------------------	---------------------

<b>Days left</b>	306
------------------	-----

<b>MOT expiry date</b>	17 March 2025
------------------------	---------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history


Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-01
Last registration	2024-03-06
Complete history	<a href="#">See info</a>



Registration #1	2010-03-01	16 mi
Registration #2	2013-02-22	36.038 mi
Registration #3	2014-02-25	47.281 mi
Registration #4	2015-03-04	59.138 mi
Registration #5	2016-03-01	71.154 mi
Registration #6	2017-02-22	82.725 mi
Registration #7	2017-02-22	82.725 mi
Registration #8	2018-07-25	96.693 mi
Registration #9	2018-07-25	96.693 mi
Registration #10	2019-10-03	102.448 mi
Registration #11	2019-10-03	102.448 mi
Registration #12	2019-10-03	102.448 mi
Registration #13	2019-10-03	102.448 mi
Registration #14	2019-10-03	102.448 mi
Registration #15	2019-10-03	102.448 mi
Registration #16	2019-10-03	102.448 mi
Registration #17	2019-10-03	102.448 mi
Registration #18	2019-10-03	102.448 mi
Registration #19	2019-10-03	102.448 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2232 mm
Height	1944 mm
Length	4782 mm
Kerb weight	1678 kg
Max. allowed weight	2770 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	C053829