





report date: 2024-03-28

### General information

Make	KIA
Model	PICANTO
Colour	White
Year of manufacture	2018
Top speed	107 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	83 BHP
Max. torque	122 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



ST68ABF report date: 2024-03-28

## Internet history

### Entry 2

Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk


Entry 1

Date	2021-01-29
D' I	22

Pictures 22

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-02-16
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	16
Total items failed	2

MOT #5		2024-01-22 11:32
MOT test	number	893456339150
Result		✓ Passed
Next expir	ry date	2025-02-16
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #4		2023-01-30 14:51
MOT test	number	417351769267
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5	.2.3 (d) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords	(5.2.3 (d) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-28

**MOT** #3 2023-01-30 10:53 789817584160 **MOT** test number Result × Failed Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2	2022-01-19 11:07
MOT test number	172580239665
Result	<b>✓</b> Passed

MOT #1	2021-02-17 09:31
MOT test number	662402069113
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	16 February 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

<b>O</b>		1- : -	A
Ow	nor	nıc	:TON

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{h}}$		
***************************************		
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR		
***************************************		
	More info >	
Plate changes		
See in this check if this KIA had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



report date: 2024-03-28

### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-09-11
Last registration	2024-01-22
Complete history	See info



Registration #1	2018-09-11	9 mi
Registration #2		11.777 es
Registration #3		11.777 es
Registration #4	2021-02-17	18.146 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.117 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

### Car features

50225	Air conditionin
50295	
60482	
0501	
0566	
0567	
60569	

## Safety ratings

NCAP rating	****
Adult	87%
Children	64%
Pedestrian	54%
Safety systems	47%
Overall rating	68%
Video	see crash video



## Dimensions & weight

Width	1595 mm
Height	1485 mm
Length	3595 mm
Wheel base	2400 mm
Kerb weight	935 kg
Max. allowed weight	1400 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11