





report date: 2024-03-28

General information

Make	ТОУОТА	
Model	VERSO VALVEMATIC TR	
Colour	Blue	
Year of manufacture	2010	
Top speed	115 mph	
0 - 60 mph	11.7 seconds	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	132 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-09-04


Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-04-24
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	19
Total items failed	11

MOT #15		2023-04-18 09:55
MOT test	number	645564803465
Result		✓ Passed
Next expi	ry date	2024-04-24
Advice	Offside Front Nail in tyre And wearing on Edges	
Advice	Rear Tyre slightly damaged/cracking or perishing Both side's on tread (5.2.3 (d)	(ii))
Advice	Rear Coil spring corroded Both side's (5.3.1 (b) (i))	
Advice	Central Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 3/14



Advice

CK10MDZ

report date: 2024-03-28

MOT #14 2023-04-18 09:55 **MOT** test number 862149317643 Result × Failed Pass with rectification Nearside Headlamp aim too low (4.1.2 (a)) **Advice** Rear Coil spring corroded Both side's (5.3.1 (b) (i)) Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Central Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) Advice Offside Front Nail in tyre And wearing on Edges Pass with rectification Offside Headlamp aim too low (4.1.2 (a)) Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #13 2022-04-15 11:02 MOT test number 325037658214

Rear Tyre slightly damaged/cracking or perishing Both side's on tread (5.2.3 (d) (ii))

Result ✓ Passed

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #12 2022-04-15 09:18

MOT test number 581771415933

Result X Failed

Fail Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Direction indicator incorrect colour (4.4.3 (a))

Advice Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Direction indicator incorrect colour (4.4.3 (a))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

MOT #11 2021-04-12 12:48

MOT test number 261131040190

Result ✓ Passed

MOT #10 2020-04-25 09:25

MOT test number 871916025238

Result ✓ Passed

MOT #9 2019-04-12 08:36

MOT test number 881848594049

Advice Offside Rear Tyre slightly damaged/cracking or perishing worn and cracking on inner edge (5.2.3

(d) (ii))

Advice Offside front tyre worn on edges

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #8 2019-04-12 07:20

MOT test number 177219360020

Result × Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing worn and cracking on inner edge (5.2.3 (d) (ii))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside front tyre worn on edges

MOT #7 2018-04-28 08:20

MOT test number 390746788068

Result ✓ Passed

MOT #6 2017-04-29 11:33

MOT test number 713027943767

Result
✓ Passed

MOT #5 2016-04-23 07:24

MOT test number 517830128717

Result

Passed

Advice Offside Rear heavily worn on inner edge

MOT #4 2015-04-22 18:18

MOT test number 259032715116

Result

Passed

MOT #3 2015-04-22 16:25

MOT test number 927652115152

Result × Failed

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

CarCheck.co.uk page 6/14



MOT #2	2014-05-03 12:05
MOT test number	765113424126
Result	✓ Passed
MOT #1	2013-03-30 11:57
MOT test number	875629183016
Result	✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	24 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14




report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

,		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		OTA

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-16
Last registration	2023-04-18
Complete history	See info



Registration #1	2010-04-16	29 mi
Registration #2	2013-03-30	60.409 mi
Registration #3	2014-05-03	63.901 mi
Registration #4	2015-04-22	59.728 mi
Registration #5	2015-04-22	59.729 mi
Registration #6	2016-04-23	71.207 mi
Registration #7	2017-04-29	74.380 mi
Registration #8	2018-04-28	78.141 mi
Registration #9	2019-04-12	81.793 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.177 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
S0482	
S0501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1505 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14

Engine number

1ZRU298322