



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 S AWD
Colour	Grey
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.5 mpg
Consumption extra urban	40.4 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-06
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	20
Total items failed	11

MOT #15	2023-07-07 07:32
MOT test number	811997223091
Result	✓ Passed
Next expiry date	2024-07-06

MOT #14	2022-06-29 08:12
MOT test number	324868156539
Result	✓ Passed

MOT #13	2021-07-07 14:54
MOT test number	689597803052
Result	✓ Passed

MOT #12	2020-09-21 09:23
MOT test number	410917847605
Result	✓ Passed

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

MOT #11	2019-08-21 14:00
MOT test number	480111476772
Result	✓ Passed

**MOT #10** 2018-08-23 10:32**MOT test number** 922578215946**Result** ✓ Passed**MOT #9** 2017-03-03 12:27**MOT test number** 829840146671**Result** ✓ Passed

Advice Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #8 2017-03-02 11:33**MOT test number** 358252735303**Result** ✗ Failed

Fail Front position lamp(s) not working both (1.1.A.3b)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Parking brake: efficiency below requirements (3.7.C.1b)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #7** 2017-03-01 15:48**MOT test number** 270577998110**Result** ✗ Failed**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**MOT #6** 2016-03-09 11:35**MOT test number** 900063659839**Result** ✓ Passed**Advice** Nearside Front Outer Tyre worn close to the legal limit 1.6mm (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2016-03-07 14:18**MOT test number** 721009520848**Result** ✗ Failed**Fail** Front Headlamp not working on dipped beam both (1.7.5a)**Advice** Nearside Front Outer Tyre worn close to the legal limit 1.6mm (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)

**MOT #4** 2014-12-01 10:46**MOT test number** 995665534341**Result** ✓ Passed**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Notice** Under-trays fitted obscuring some underside components**Notice** Nail in nearside rear tyre**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2013-11-29 16:26**MOT test number** 328533333322**Result** ✓ Passed**Notice** Both wipper blade slightly split**Notice** Non obligatory mirror damaged**MOT #2** 2013-01-18 11:55**MOT test number** 155898713045**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2012-02-06 09:34**MOT test number** 485147432015**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
6 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-03
Last registration	2023-07-07
Complete history	See info



Registration #1	2009-03-03	7 mi
Registration #2	2012-02-06	30.244 mi
Registration #3	2013-01-18	34.537 mi
Registration #4	2013-11-29	39.143 mi
Registration #5	2014-12-01	45.383 mi
Registration #6	2016-03-07	54.801 mi
Registration #7	2016-03-09	54.802 mi
Registration #8	2017-03-01	60.263 mi
Registration #9	2017-03-02	60.270 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1743 mm
Length	4798 mm
Wheel base	2857 mm
Kerb weight	2135 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	692724