





report date: 2024-03-29

## General information

Make	PEUGEOT
Model	206 D TURBO HDI (90BHP)
Colour	Silver
Year of manufacture	2001
Top speed	112 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	68.9 mpg
Consumption combined	56.5 mpg
CO2 emission	136 g/km
CO2 lahel	F



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history

# Entry 2

Date 2023-10-17

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk


Entry 1

Date	2021-06-12
D' I	10

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



HD51RGY report date: 2024-03-29

2023-08-18 12-01

MOT history

MOT #21

MOT expiry date	2024-08-21
MOT pass rate	86 %
MOT passed	19
Failed MOT tests	3
Total advice items	12
Total items failed	7

MOT #22	2023-08-22 10:23
MOT test number	378664081346
Result	✓ Passed
Next expiry date	2024-08-21

MOI #	-21	2023-00-10 12.01
MOT to	est number	760597638559
Result		<b>X</b> Failed
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail	Rear Seat belt missing (7.1.2 (a))	
Fail	Offside Headlamp not working on main beam (4.1.1 (a) (ii))	

MOT #20	2022-06-07 14:41
MOT test number	449105952513
Result	✓ Passed
MOT #10	2022 06 07 12 26

MOT #19		2022-06-07 12:36
MOT test number		183706609907
Result		<b>X</b> Failed
	sions exceed level of metered smoke for a turbo charges excessive smoke or vapour likely to obscure the vision	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #18 2021-06-10 15:31

**MOT test number** 750885487374

**Result** 
✓ Passed

MOT #17 2020-10-26 12:51

MOT test number 151401574747

Result 

Passed

MOT #16 2019-10-11 09:55

MOT test number 591084995110

**Result** 
✓ Passed

**Advice** Offside Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair foot brake and park effort (1.2.1 (c))

Advice Offside Front Side repeater slightly discoloured (4.4.3 (a))

**MOT #15** 2018-10-09 09:05

**MOT test number** 782863088121

Result Passed

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #14** 2017-10-12 11:51

MOT test number 893851851143

Result \( \sqrt{Passed} \)

**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #13 2016-10-12 11:31

**MOT test number** 205035553194

CarCheck.co.uk page 4/13



Result

**HD51RGY** 

report date: 2024-03-29

✓ Passed

MOT #12	2015-10-16 16:03
MOT test number	704674039837
Result	✓ Passed
MOT #11	2014-10-20 08:27
MOT test number	788563394216
Result	✓ Passed
Advice Offside Front Shock absorber has a light misting of oil (2.7.3)	
MOT #10	2013-10-16 14:32
MOT test number	756899783260
Result	<b>✓</b> Passed
MOT #9	2012-10-12 15:36
MOT test number	198626182216
Result	✓ Passed
MOT #8	2011-10-04 15:04
MOT test number	397267471237
Result	✓ Passed
MOT #7	2010-10-08 12:09
MOT test number	164731780292
Result	✓ Passed
MOT #6	2009-10-09 12:38
MOT test number	681572989218

CarCheck.co.uk page 5/13



report date: 2024-03-29

**MOT #5** 2008-10-07 12:39

**MOT test number** 332511588215

MOT #4 2007-10-15 12:32

MOT test number 382798187407

**Result** ✓ Passed

**Notice** Slight play nearside front lower ball joint.

MOT #3 2007-10-15 09:42

**MOT test number** 570268087269

Result X Failed

**Fail** Offside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

**Notice** Slight play nearside front lower ball joint.

Fail Offside Front brake disc excessively pitted (3.5.1h)

MOT #2 2006-10-09 15:22

**MOT test number** 523462986254

Result \sqrt{Passed}

**Advice** Nearside Front brake disc slightly pitted (3.5.1h)

**Advice** Offside Front brake disc slightly pitted (3.5.1h)

**MOT #1** 2005-10-10 15:28

MOT test number 493173785201

Result 

Passed

**Advice** Nearside Front brake disc slightly pitted (3.5.1h)

**Advice** Offside Front brake disc slightly pitted (3.5.1h)

CarCheck.co.uk page 6/13



HD51RGY report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	21 August 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

## Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



HD51RGY report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



factor scincol

HD51RGY

report date: 2024-03-29

# For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this PEUGEOT had different number plates.

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

## Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2001-10-31
Last registration	2023-08-22
Complete history	See info



Registration #1	2001-10-31	11 mi
Registration #2	2005-10-10	5.580 mi
Registration #3	2006-10-09	7.057 mi
Registration #4	2007-10-15	7.784 mi
Registration #5	2008-10-07	8.428 mi
Registration #6	2009-10-09	8.928 mi
Registration #7	2010-10-08	9.370 mi
Registration #8	2011-10-04	9.875 mi
Registration #9	2012-10-12	10.956 mi
Registration #10	2013-10-16	12.383 mi
Registration #11	2014-10-20	13.034 mi
Registration #12	2015-10-16	13.668 mi
Registration #13		73.777 es
Registration #14		11.771 46
		11.777 ea 11.777 ea
Registration #14		11.777 ea 11.777 ea
Registration #14 Registration #15		11.777 es 11.777 es 11.777 es
Registration #14 Registration #15 Registration #16		11.77 es 11.77 es 11.77 es
Registration #14 Registration #15 Registration #16 Registration #17		11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm

# Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of axles	2
Engine number	DYGX3039994

CarCheck.co.uk page 13/13