



report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2014
Top speed	98 mph
0 - 60 mph	5.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.6 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history


Entry 3

Date	2023-09-06
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 2


Date	2021-10-29
Pictures	20
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-08-28
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-18
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	19
Total items failed	9

MOT #11	2023-09-19 14:48
MOT test number	520099665488
Result	✓ Passed
Next expiry date	2024-09-18

MOT #10	2023-01-27 09:34
MOT test number	661750489767
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #9**

2023-01-27 08:55

MOT test number

393317873611

Result**✗ Failed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #8**

2022-01-28 15:25

MOT test number

777356246050

Result**✓ Passed****Advice** R/n/s tyre perishing**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #7**

2022-01-26 16:16

MOT test number

250640594977

Result**✗ Failed****Advice** Damage to r/n/s light lens**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Fail** Hazard warning switch inoperative (4.4.2 (a) (ii))**Advice** R/n/s tyre perishing**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6** 2020-10-21 13:06**MOT test number** 766955915836**Result** ✓ Passed**MOT #5** 2020-10-19 08:30**MOT test number** 123052693737**Result** ✗ Failed**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure Lumps in outer wall (5.2.3 (d) (ii))**Fail** Nearside Front Body panel damaged and likely to cause injury Accident damage (6.2.1 (a) (i))**Fail** Horn not working (7.7 (a) (ii))**Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure Lumps in outer wall (5.2.3 (d) (ii))**MOT #4** 2019-10-23 08:22**MOT test number** 828526443282**Result** ✓ Passed**Advice** Offside Front wiper slightly smearing screen**Advice** Nearside Front Tyre slightly damaged on side wall (5.2.3 (d) (ii))**Advice** Parking brake lever has low reserve travel**MOT #3** 2018-10-11 14:20**MOT test number** 699966344145**Result** ✓ Passed**MOT #2** 2017-10-02 10:10**MOT test number** 256079576014**Result** ✓ Passed



MOT #1	2017-10-02 10:10
MOT test number	853002906148
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too high (1.8)
Pass with rectification	Offside Front Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
18 September 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	18 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-10-24
Last registration	2023-09-19
Complete history	See info



Registration #1	2014-10-24	22 mi
Registration #2	2017-10-02	7.334 mi
Registration #3	2017-10-02	7.334 mi
Registration #4	2018-10-11	10.817 mi
Registration #5	2019-10-23	14.277 mi
Registration #6	2020-10-19	16.673 mi
Registration #7	2020-10-21	16.674 mi
Registration #8	2020-10-21	16.674 mi
Registration #9	2020-10-21	16.674 mi
Registration #10	2020-10-21	16.674 mi
Registration #11	2020-10-21	16.674 mi
Registration #12	2020-10-21	16.674 mi
Registration #13	2020-10-21	16.674 mi
Registration #14	2020-10-21	16.674 mi
Registration #15	2020-10-21	16.674 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1365 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	5556399