





report date: 2024-03-28

### General information

Make	CITROEN
Model	NEMO 660 ENTERPRISE HDI
Colour	White
Year of manufacture	2016
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	80 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

Entry 1	

Lifety 1	
Date	2021-12-23
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-05-22
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #6	2023-05-23 16:07
MOT test number	170740355004
Result	✓ Passed
Next expiry date	2024-05-22

MOT #5	2022-10-25 09:15
MOT test number	943009979253
Result	✓ Passed

MOT #4	2021-10-20 08:13
MOT test number	528185384710
Result	✓ Passed
Advice Offside Front Upper strut top bearing stiff in operation	

MOT #3		2020-09-30 12:04
MOT test	number	219147226617
Result		✓ Passed
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Nearside Front Upper strut top bearing stiff in operation	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



(b) (ii))

SL66EVV report date: 2024-03-28

**MOT #2** 2020-09-30 12:04

**MOT test number** 257225838286

Result × Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**Advice** Nearside Front Upper strut top bearing stiff in operation

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4

MOT #1 2019-10-29 09:29

**MOT test number** 420146965096

Result \( \sqrt{Passed} \)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check





Tax status	Expired at 1 December 2023
Days left	149 days too late
MOT expiry date	22 May 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		OEN
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	UK UK	TITE
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-11-30
Last registration	2023-05-23
Complete history	See info



Registration #1	2016-11-30	7 mi
Registration #2	2019-10-29	25.697 mi
Registration #3	2020-09-30	31.220 mi
Registration #4	2020-09-30	31.220 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



## Safety ratings

NCAP rating	***
Adult	59%
Children	74%
Pedestrian	55%
Safety systems	29%
Overall rating	58%
Video	see crash video



# Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	00006166744

CarCheck.co.uk page 11/11