



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 XC70 D5 AWD SE LUX EU4
Colour	Grey
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.2 mpg
CO2 emission	219 g/km
CO2 label	K





MOT history

MOT expiry date	2025-04-14
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	9
Total items failed	9

MOT #17	2024-04-15 14:12
MOT test number	426286775061
Result	✓ Passed
Next expiry date	2025-04-14

MOT #16	2021-05-07 08:38
MOT test number	226915274628
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #15	2020-02-14 16:23
MOT test number	442619539320
Result	✓ Passed

MOT #14	2020-02-14 13:07
MOT test number	629501106615
Result	✗ Failed
Fail	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #13** 2019-02-09 14:41**MOT test number** 153884210903**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2019-02-08 13:22**MOT test number** 501967556907**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-02-22 10:28**MOT test number** 972696625228**Result** ✓ Passed**Advice** Nearside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Engine management light illuminated indicating a fault**MOT #10** 2017-03-01 14:05**MOT test number** 800049989104**Result** ✓ Passed

**MOT #9** 2017-03-01 11:35**MOT test number** 997749791804**Result** ✗ Failed**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**MOT #8** 2016-06-07 16:09**MOT test number** 292633834071**Result** ✓ Passed**MOT #7** 2016-06-01 09:22**MOT test number** 991089692782**Result** ✗ Failed**Fail** Nearside Side repeater missing (1.4.A.2b)**Fail** Offside Front Outer Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2014-12-10 12:03**MOT test number** 998674444384**Result** ✓ Passed**MOT #5** 2014-12-10 12:03**MOT test number** 959214544371**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #4** 2013-11-28 12:15**MOT test number** 416822933310**Result** ✓ Passed



MOT #3	2012-10-30 09:33
MOT test number	817684602343
Result	✓ Passed
MOT #2	2011-11-10 11:59
MOT test number	987224211394
Result	✓ Passed
MOT #1	2010-11-09 14:55
MOT test number	193123710351
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
14 April 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	14 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-11-14
Last registration	2024-04-15
Complete history	See info



Registration #1	2007-11-14	8 mi
Registration #2	2010-11-09	27.449 mi
Registration #3	2011-11-10	33.686 mi
Registration #4	2012-10-30	36.310 mi
Registration #5	2013-11-28	46.764 mi
Registration #6	2014-12-10	53.335 mi
Registration #7	2016-06-01	68.244 mi
Registration #8	2016-06-07	68.244 mi
Registration #9	2017-03-01	76.606 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2100 mm
Height	1562 mm
Length	4733 mm
Wheel base	2763 mm
Kerb weight	1877 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	572691