



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	Blue
Year of manufacture	2011
Top speed	93 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	110 g/km
CO2 label	B





MOT history

MOT expiry date	2024-03-28
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	24
Total items failed	16

MOT #12	2023-03-29 15:37
MOT test number	333214610304
Result	✓ Passed
Next expiry date	2024-03-28
Advice	Offside Rear Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))
Advice	Rear wiper blade split
Advice	Brake pipe corroded, covered in grease or other material o/s/r front to rear (1.1.11 (c))

**MOT #11**

2023-03-24 12:55

**MOT test number**

211316746193

**Result****✗ Failed**

- Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material o/s/r front to rear (1.1.11 (c))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))
- Advice** Rear wiper blade split

**MOT #10**

2022-03-21 09:57

**MOT test number**

693572277624

**Result****✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))
- Minor** Windscreen wiper blade defective (3.4 (b) (i))

**MOT #9** 2021-01-07 13:34**MOT test number** 580776532306**Result** ✓ Passed**MOT #8** 2019-07-20 11:06**MOT test number** 311202262805**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-06-28 12:26**MOT test number** 347542133646**Result** ✓ Passed**MOT #6** 2018-06-27 16:37**MOT test number** 640565437589**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #5** 2017-07-28 11:59**MOT test number** 868823971307**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Outer brake disc worn, pitted or scored, but not seriously weakened poor condition (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin all pads (3.5.1g)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2016-04-23 09:05**MOT test number** 206197147409**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front (2.4.G.2)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #3** 2016-04-23 09:05**MOT test number** 300627049124**Result** ✗ Failed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Pass with rectification** Nearside Rear Valve stem seriously damaged (4.1.D.1e)
- Advice** Offside Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front (2.4.G.2)

**MOT #2** 2015-04-14 09:47**MOT test number** 237754905145**Result** ✓ Passed



MOT #1	2014-04-17 09:02
MOT test number	258087304498
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 April 2024

X

MOT

Expired:  
28 March 2024

Tax status	Expired at 1 April 2024
Days left	27 days too late
MOT expiry date	28 March 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YR11KND
Plate since	2019-09-29
Current registration	YR11KND
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-04-26
Last registration	2023-03-29
Complete history	<a href="#">See info</a>



Registration #1	2011-04-26	21 mi
Registration #2	2014-04-17	27.688 mi
Registration #3	2015-04-14	38.809 mi
Registration #4	2016-04-23	49.446 mi
Registration #5	2016-04-23	49.446 mi
Registration #6	2017-07-28	69.770 mi
Registration #7	2018-06-27	84.349 mi
Registration #8	2019-05-29	95.277 mi
Registration #9	2019-05-29	95.277 mi
Registration #10	2019-05-29	95.277 mi
Registration #11	2019-05-29	95.277 mi
Registration #12	2019-05-29	95.277 mi
Registration #13	2023-03-29	95.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	1KR1232499