



report date: 2024-03-29

General information

Make	NISSAN
Model	MICRA ACENTA
Colour	Blue
Year of manufacture	2014
Top speed	101 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed CVT

Engine & fuel consumption

Power	79 BHP
Max. torque	142 Nm at 4.400 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	125 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-03-07
Pictures	11
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-19
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	19
Total items failed	0

MOT #10 2024-03-18 14:29

MOT test number 915840398944

Result ✓ Passed

Next expiry date 2025-03-19

Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #9 2023-03-20 10:55

MOT test number 747955036372

Result ✓ Passed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #8 2022-03-17 14:04

MOT test number 607671662928

Result ✓ Passed

**MOT #7**

2022-03-15 11:48

MOT test number

793661007302

Result**✗ Failed**

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement forward facing bush (5.3.4 (a) (i))

MAJOR Offside Rear Brake pipe excessively corroded to brake hose (1.1.11 (c))

MAJOR Nearside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))

Advice Nearside Front Nail in tyre

MAJOR Nearside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement forward facing bush (5.3.4 (a) (i))

MAJOR Nearside Rear Brake pipe excessively corroded to brake hose (1.1.11 (c))

Advice Oil leak, but not excessive porous sump (8.4.1 (a) (i))

MAJOR Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))

MAJOR Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))

MOT #6

2021-03-10 11:25

MOT test number

129350095842

Result**✓ Passed****MOT #5**

2021-03-04 12:44

MOT test number

889610309299

Result**✗ Failed**

MAJOR Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #4** 2020-07-22 13:19**MOT test number** 687209594475**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #3** 2019-07-25 10:12**MOT test number** 514689692044**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MOT #2** 2018-07-31 08:48**MOT test number** 849694357829**Result** ✓ Passed**MOT #1** 2017-08-11 09:40**MOT test number** 245265694830**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
19 March 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	19 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-01
Last registration	2024-03-18
Complete history	See info



Registration #1	2014-09-01	11 mi
Registration #2	2017-08-11	21.172 mi
Registration #3	2018-07-31	25.037 mi
Registration #4	2019-07-25	29.824 mi
Registration #5	2020-07-22	32.971 mi
Registration #6	2021-03-04	33.897 mi
Registration #7	2022-03-20	35.277 mi
Registration #8	2023-03-20	36.277 mi
Registration #9	2024-03-20	37.277 mi
Registration #10	2025-03-20	38.277 mi
Registration #11	2026-03-20	39.277 mi
Registration #12	2027-03-20	40.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	79%
Pedestrian	58%
Safety systems	57%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1665 mm
Height	1520 mm
Length	3825 mm
Wheel base	2450 mm
Kerb weight	945 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

92463A