





report date: 2024-03-28

General information

| Make | MINI |
|---------------------|----------------|
| Model | MINI (R60) ONE |
| Colour | Blue |
| Year of manufacture | 2012 |
| Top speed | 107 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 98 BHP |
|-------------------------|---------------------|
| Max. torque | 153 Nm at 3.000 rpm |
| Engine capacity | 1.598 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-01-26

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-07-02 |
|--------------------|------------|
| MOT pass rate | 90 % |
| MOT passed | 9 |
| Failed MOT tests | 1 |
| Total advice items | 19 |
| Total items failed | 4 |

| MOT #10 | | 2023-07-03 15:39 |
|--|---|------------------|
| MOT test | number | 999177416021 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-07-02 |
| Advice | Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a)) | |
| Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i)) | | |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |
| Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i)) | | |

| MOT #9 | 2022-01-06 15:25 |
|-----------------|------------------|
| MOT test number | 344330897166 |
| Result | ✓ Passed |

| MOT #8 | | 2020-12-22 16:44 |
|----------|--|------------------|
| MOT test | number | 521652149469 |
| Result | | ✓ Passed |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/12



MOT #7 2020-01-03 08:53
MOT test number 652361988037

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2019-01-09 10:22

MOT test number 196777706048

Result \rightarrow Passed

MOT #5 2018-02-24 10:27

MOT test number 874265220361

Result \rightarrow Passed

Advice Oil leak

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Nearside Rear Tyre worn close to the legal limit tyre perished and worn lumpy to inner edge

(4.1.E.1)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 4/12



Passed

MOT #4 2018-02-24 10:27

MOT test number 268278581586

Result X Failed

Pass with rectification Nearside Front Headlamp aim too low (1.8)

Advice Nearside Rear Tyre worn close to the legal limit tyre perished and worn lumpy to inner edge (4.1.E.1)

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Oil leak

Pass with rectification Offside Front Headlamp aim too low (1.8)

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Vehicles internal headlight adjuster altered to recheck lights

MOT #3 2017-02-21 17:30

MOT test number 533132866012

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2016-02-17 14:24

MOT test number 815530712501

Result
✓ Passed

MOT #1 2015-02-25 08:36

MOT test number 938346555020

Result

Passed

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 January |
|------------------|-----------------------|
| Days left | 248 |
| MOT expiry date | 2 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | Е |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 6/12



YS12DTX

report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



YS12DTX

report date: 2024-03-28

| _ | |
|-------|-----------|
| Owner | hictory |
| OWITE | HIISLUH V |

| o mile motory | |
|--|-------------|
| For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report | |
| ********* | |
| *************************************** | |
| THE PROPERTY OF THE PROPERTY O | |
| *************************************** | |
| *************************************** | |
| THE STREET STREET | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | |
| Current registration | ZIS UK |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |
| | Hore into / |

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2012-06-01 |
| Last registration | 2023-07-03 |
| Complete history | See info |



| Registration #1 | 2012-06-01 | 7 mi |
|------------------|------------|-----------|
| Registration #2 | 2015-02-25 | 26.886 mi |
| Registration #3 | 2016-02-17 | 34.039 mi |
| Registration #4 | 2017-02-21 | 41.930 mi |
| Registration #5 | 2018-02-24 | 48.041 mi |
| Registration #6 | 2018-02-24 | 48.041 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 9.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | m |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 1789 mm |
|---------------------|---------|
| Height | 1561 mm |
| Length | 4097 mm |
| Wheel base | 2595 mm |
| Kerb weight | 1265 kg |
| Max. allowed weight | 1775 kg |

Additional information

| Fuel tank capacity | 47 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

Number of axles2Engine numberB409J297