



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Black
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-09-25
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-16
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	39
Total items failed	8

MOT #16	2023-10-17 07:29
MOT test number	612382998637
Result	✓ Passed
Next expiry date	2024-10-16
Advice	Nearside Rear Seat belt buckle stiff but works
Advice	Shock absorbers has light misting of oil

MOT #15	2023-10-10 07:05
MOT test number	396090230765
Result	✗ Failed
Advice	Nearside Rear Seat belt buckle stiff but works
Fail	Oil leaking excessively from engine (8.4.1 (a) (i))
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Advice	Shock absorbers has light misting of oil

**MOT #14**

2022-10-11 11:33

MOT test number

168994425369

Result

✓ Passed

- Advice** Front Play in steering rack inner joint(s)
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Bottom arm rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Seat belt buckle stiff but works
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Tyre worn edges (5.2.3 (e))

MOT #13

2022-10-05 10:08

MOT test number

667570304918

Result

✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Bottom arm rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Seat belt buckle stiff but works
- Fail** Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Tyre worn edges (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Play in steering rack inner joint(s)
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #12

2021-10-08 12:11

MOT test number

184044975790

Result

✓ Passed

**MOT #11** 2020-12-08 14:14**MOT test number** 324829079954**Result** ✓ Passed**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**Advice** Both front tyres are starting to wear low**MOT #10** 2020-11-27 15:40**MOT test number** 384935301167**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Front Headlamp aim too low (4.1.2 (a))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Rear Stop lamp(s) switch does not operate in accordance with the requirements high level stop light (4.3.2 (a) (i))**MOT #9** 2019-10-31 16:38**MOT test number** 563464972307**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-11-23 14:37**MOT test number** 518372397850**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2017-11-25 09:31**MOT test number** 965252241480**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Offside Rear Inner tyre worn smooth inner shoulder**Advice** High level stamp loose**MOT #6** 2017-11-25 09:06**MOT test number** 252159999429**Result** ✗ Failed**Advice** Offside Rear Inner tyre worn smooth inner shoulder**Fail** Nearside Rear Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)**Advice** High level stamp loose**Advice** Offside Rear Nail in tyre**MOT #5** 2016-11-24 09:32**MOT test number** 959393613042**Result** ✓ Passed**MOT #4** 2015-11-02 11:43**MOT test number** 815822755412**Result** ✓ Passed**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #3** 2014-11-07 10:52**MOT test number** 648571014310**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2013-11-22 13:48**MOT test number** 857406323316**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2012-11-26 14:10**MOT test number** 425201932451**Result** ✓ Passed**Notice** Both nearside tyres damaged on the wall



Tax & MOT check

X

Untaxed

Tax expired:
29 February 2024

✓

MOT

Expires:
16 October 2024

Tax status	Expired at 29 February 2024
Days left	61 days too late
MOT expiry date	16 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-23
Last registration	2023-10-17
Complete history	See info



Registration #1	2009-11-23	16 mi
Registration #2	2012-11-26	31.734 mi
Registration #3	2013-11-22	41.191 mi
Registration #4	2014-11-07	51.265 mi
Registration #5	2015-11-02	61.072 mi
Registration #6	2016-11-24	71.335 mi
Registration #7	2017-11-25	80.418 mi
Registration #8	2017-11-25	80.418 mi
Registration #9	2018-11-23	91.632 mi
Registration #10	2019-11-23	102.846 mi
Registration #11	2020-11-23	114.060 mi
Registration #12	2021-11-23	125.274 mi
Registration #13	2022-11-23	136.488 mi
Registration #14	2023-11-23	147.702 mi
Registration #15	2024-11-23	158.916 mi
Registration #16	2025-11-23	170.130 mi
Registration #17	2026-11-23	181.344 mi
Registration #18	2027-11-23	192.558 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1943 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	9G39426