






report date: 2024-03-28

General information

Make	AUDI
Model	A1 TFSI SPORT
Colour	Black
Year of manufacture	2016
Top speed	116 mph
0 - 100 km/h	10.9 seconds
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 kW / 95 HP / 94 BHP
Max. torque	160 Nm at 1.500 rpm
Engine capacity	999 сс
Cylinders	3
Fuel type	Petrol
Consumption city	56.5 mpg
Consumption extra urban	76.3 mpg
Consumption combined	67.3 mpg
CO2 emission	97 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



report date: 2024-03-28


Internet history

Entry 1

Date 2021-07-10

Pictures 32

Listing price <u>View report</u>









source: heycar.co.uk

CarCheck.co.uk page 2/11



DF66RHA
report date: 2024-03-28

MOT history

MOT expiry date	2025-03-17
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #7	2024-03-18 16:14
MOT test number	887768086776
Result	✓ Passed
Next expiry date	2025-03-17

MOT #6	2023-05-19 11:28
MOT test number	769246278445
Result	✓ Passed

MOT #F		2022 05 25 00 20
MOT #5		2022-05-25 08:38
MOT test	number	734235702238
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))

MOT #4	2021-06-05 11:32
MOT test number	119466007112
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

Passed

MOT #3 2020-11-13 15:12

MOT test number 265922719799

Advice

Result

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2019-11-11 21:56

MOT test number 686157029673

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2019-11-07 21:24

MOT test number 596851147686

Result × Failed

Fail Nearside Front Inner Suspension arm pin or bush excessively worn separating from arm housing (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Front Inner Suspension arm pin or bush excessively worn separating from arm housing (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



DF66RHA
report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	17 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11




report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



DF66RHA
report date: 2024-03-28

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report I	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	UK AIG AIG
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-11-16
Last registration	2024-03-18
Complete history	See info



Registration #1	2016-11-16	9 mi
Registration #2	2019-11-07	16.980 mi
Registration #3	2019-11-11	16.980 mi
Registration #4	2020-11-13	23.290 mi
Registration #5	2021-06-05	26.071 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	90%
Children	79%
Pedestrian	49%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1906 mm
Height	1416 mm
Length	3973 mm
Wheel base	2469 mm
Kerb weight	1010 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	3
Number of axles CarCheck.co.uk	2 page 11/1

Engine number

CHZB169434