



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Black
Year of manufacture	2014
Top speed	120 mph
0 - 100 km/h	10.9 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-05-26
Pictures	33
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-05-31
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	27
Total items failed	9

MOT #13	2023-05-30 08:44
MOT test number	565725368339
Result	✓ Passed
Next expiry date	2024-05-31
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #12	2023-05-30 08:00
MOT test number	397651900385
Result	✗ Failed
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice	BRAKE PAD WEAR WARNING LIGHT ON

MOT #11	2022-05-31 08:39
MOT test number	913297509694
Result	✓ Passed

**MOT #10** 2022-05-31 08:14**MOT test number** 451368458404**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Front Windscreen washer not working (3.5 (a))**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions NOT THE ROTATION ON TYRE (5.2.3 (i))**MOT #9** 2021-06-01 13:36**MOT test number** 253662741437**Result** ✓ Passed**MOT #8** 2020-08-11 13:47**MOT test number** 902342202026**Result** ✓ Passed**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7** 2020-08-11 10:59**MOT test number** 194994006332**Result** ✗ Failed

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Fail** Registration plate lamp likely to become detached (4.7.1 (c) (ii))

**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #6** 2019-08-09 13:50**MOT test number** 898995105251**Result** ✓ Passed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both sides trailing arms (5.3.4 (a) (i))

**MOT #5** 2019-08-08 15:30**MOT test number** 146904264044**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both sides trailing arms (5.3.4 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Tyre slightly damaged/cracking or perishing rear both (5.2.3 (d) (ii))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Rear Passenger seat(s) missing at time of test centre n o/s/r folded**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #4** 2018-07-26 16:56**MOT test number** 864085336133**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #3** 2017-08-18 09:14**MOT test number** 418048431632**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin near side and off side (3.5.1g)



MOT #2	2017-08-17 12:28
MOT test number	760085270490
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin near side and off side (3.5.1g)
Fail	Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #1	2016-11-18 12:19
MOT test number	174196765765
Result	✓ Passed
Advice	Under trays fitted



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
31 May 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	31 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	NV63KFD
Plate since	2019-03-28
Current registration	NV63KFD
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-01-29
Last registration	2023-05-30
Complete history	<a href="#">See info</a>



Registration #1	2014-01-29	14 mi
Registration #2	2016-11-18	14.842 mi
Registration #3	2017-08-17	17.916 mi
Registration #4	2017-08-18	17.921 mi
Registration #5	2018-07-26	27.216 mi
Registration #6	2019-08-08	34.885 mi
Registration #7	2019-08-09	34.885 mi
Registration #8	2020-08-11	42.115 mi
Registration #9	2020-08-11	42.115 mi
Registration #10	2020-08-11	42.115 mi
Registration #11	2020-08-11	42.115 mi
Registration #12	2020-08-11	42.115 mi
Registration #13	2020-08-11	42.115 mi
Registration #14	2020-08-11	42.115 mi
Registration #15	2020-08-11	42.115 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1688 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	ET47075