



SNI4VZT

report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SPORT
Colour	Silver
Year of manufacture	2014
Top speed	121 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	147 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-05
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-08
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	7
Total items failed	0

MOT #9	2023-06-09 10:23
MOT test number	257106018936
Result	✓ Passed
Next expiry date	2024-06-08
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8	2022-07-04 08:55
MOT test number	753267071112
Result	✓ Passed

MOT #7	2021-07-23 05:49
MOT test number	725688025724
Result	✓ Passed

MOT #6	2021-07-19 12:02
MOT test number	240567258492
Result	✗ Failed
MAJOR	Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
DANGEROUS	Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #5** 2021-03-03 12:31**MOT test number** 480736756068**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.50mm (5.2.3 (e))**MOT #4** 2020-02-26 13:34**MOT test number** 186880717521**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush slightly split away from outer casing. (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush slightly split away from outer casing (5.3.4 (a) (i))**MOT #3** 2019-02-26 09:21**MOT test number** 763349084994**Result** ✓ Passed**MOT #2** 2018-02-20 11:34**MOT test number** 904049485452**Result** ✓ Passed**MOT #1** 2017-02-22 12:29**MOT test number** 825113139025**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
8 June 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-01
Last registration	2023-06-09
Complete history	See info



Registration #1	2014-03-01	17 mi
Registration #2	2017-02-22	9.340 mi
Registration #3	2018-02-20	18.777 mi
Registration #4	2019-02-26	31.773 mi
Registration #5	2020-02-26	43.395 mi
Registration #6	2021-03-03	52.434 mi
Registration #7	2022-03-03	55.277 mi
Registration #8	2022-03-03	55.277 mi
Registration #9	2022-03-03	55.277 mi
Registration #10	2022-03-03	55.277 mi
Registration #11	2023-06-09	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3890 mm
Wheel base	2430 mm
Kerb weight	1130 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1822975