



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 PURETECH DSTYLE PLUS S/S
Colour	Blue
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	9.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	104 g/km
CO2 label	B







Internet history

Entry 2

Date	2022-01-18
Pictures	44
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-17
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-09
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	12
Total items failed	5

MOT #10	2024-02-05 12:09
MOT test number	857998904544
Result	✓ Passed
Next expiry date	2025-02-09
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #9	2024-02-03 11:43
MOT test number	924218894876
Result	✗ Failed
Fail	Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8	2023-01-30 15:34
MOT test number	520849373874
Result	✓ Passed

**MOT #7** 2023-01-30 15:34**MOT test number** 497350554129**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #6** 2022-02-10 10:32**MOT test number** 340620432169**Result** ✓ Passed**MOT #5** 2022-02-03 08:37**MOT test number** 730398497822**Result** ✗ Failed**Fail** Rear Exhaust system insecure (6.1.2 (a))**MOT #4** 2021-05-19 13:13**MOT test number** 859233773595**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2020-05-20 08:25**MOT test number** 333350760136**Result** ✓ Passed**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing Sidewall. (5.2.3 (d) (ii))**Advice** Offside Rear Nail in tyre**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing Sidewall (5.2.3 (d) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #2	2019-05-15 09:46
MOT test number	988823786537
Result	✓ Passed
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))

MOT #1	2018-05-30 08:03
MOT test number	442748229172
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
9 February 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-29
Current registration	 
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-05-31
Last registration	2024-02-05
Complete history	See info



Registration #1	2015-05-31	14 mi
Registration #2	2018-05-30	20.099 mi
Registration #3	2019-05-15	25.453 mi
Registration #4	2020-05-20	29.461 mi
Registration #5	2021-05-19	32.589 mi
Registration #6	2022-05-20	35.717 mi
Registration #7	2023-05-20	38.845 mi
Registration #8	2024-02-05	41.973 mi
Registration #9		
Registration #10		
Registration #11		
Registration #12		
Registration #13		

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1070 kg
Max. allowed weight	1578 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	XV120080873