



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	VERSO VALVEMATIC TR
Colour	Silver
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	7 speed CVT

Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-03
Pictures	6
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-23
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	49
Total items failed	19

MOT #19	2023-08-24 17:28
MOT test number	404606416632
Result	✓ Passed
Next expiry date	2024-08-23
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both sides (6.1.1 (c) (i))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Brake disc worn, but not excessively both sides (1.1.14 (a) (i))
Advice	Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))

**MOT #18**

2023-08-17 16:05

**MOT test number**

227976921250

**Result****✗ Failed**

- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material both side (1.1.11 (c))
- Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Brake pad(s) wearing thin both side (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** General under body / suspension has slight corrosion all around
- Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Fuel Pipe/s corroded

**MOT #17**

2022-08-19 12:39

**MOT test number**

773682240409

**Result****✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Rear Lower Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #16**

2022-08-19 12:39

**MOT test number**

925377993194

**Result**

✗ Failed

**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Lower Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**MOT #15**

2021-09-30 13:37

**MOT test number**

526030620105

**Result**

✓ Passed

**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2021-09-01 15:58

**MOT test number**

887892891518

**Result****✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases backbox (6.1.2 (a))
- Fail** Windscreen wiper not working Both (3.4 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2020-08-26 08:56

**MOT test number**

615701882776

**Result****✓ Passed****MOT #12**

2020-08-25 10:49

**MOT test number**

136953957277

**Result****✗ Failed**

- Pass with rectification** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Rear Coil spring insecure (5.3.1 (a) (i))
- Pass with rectification** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #11** 2019-09-04 15:11**MOT test number** 365903551720**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10** 2018-09-14 15:38**MOT test number** 455022661195**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2018-09-12 10:15**MOT test number** 118800100005**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2017-09-05 13:39**MOT test number** 212014567039**Result** ✓ Passed**Advice** Rear tyres perished and have various small cuts**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7** 2016-09-10 11:10**MOT test number** 951025955573**Result** ✓ Passed

- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2016-09-03 08:35**MOT test number** 395047229568**Result** ✗ Failed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

**MOT #5** 2015-09-15 11:27**MOT test number** 449804991237**Result** ✓ Passed

- Advice** OSF wiper poor
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



**MOT #4** 2015-09-15 11:26**MOT test number** 313229442976**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** OSF wiper poor**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #3** 2014-08-29 09:47**MOT test number** 115841444202**Result** ✓ Passed**MOT #2** 2013-08-28 16:34**MOT test number** 609200943281**Result** ✓ Passed**MOT #1** 2012-08-17 09:37**MOT test number** 308620032477**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
23 August 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	23 August 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	EX59YGA
Plate since	2019-09-29
Current registration	EX59YGA
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-02
Last registration	2023-08-24
Complete history	<a href="#">See info</a>



Registration #1	2009-09-02	21 mi
Registration #2	2012-08-17	38.868 mi
Registration #3	2013-08-28	52.818 mi
Registration #4	2014-08-29	68.317 mi
Registration #5	2015-09-15	81.500 mi
Registration #6	2015-09-15	81.500 mi
Registration #7	2016-09-03	93.276 mi
Registration #8	2016-09-10	93.437 mi
Registration #9	2017-09-05	105.982 mi
Registration #10	2018-09-12	117.209 mi
Registration #11	2018-09-14	117.258 mi
Registration #12	2019-09-01	117.258 mi
Registration #13	2019-09-01	117.258 mi
Registration #14	2019-09-01	117.258 mi
Registration #15	2019-09-01	117.258 mi
Registration #16	2019-09-01	117.258 mi
Registration #17	2019-09-01	117.258 mi
Registration #18	2019-09-01	117.258 mi
Registration #19	2019-09-01	117.258 mi
Registration #20	2019-09-01	117.258 mi
Registration #21	2019-09-01	117.258 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2



Engine number

1ZZU146847