



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOUAREG SE TDI DPF
Colour	Black
Year of manufacture	2007
Top speed	114 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	172 BHP
Max. torque	400 Nm at 2.250 rpm
Engine capacity	2.461 cc
Cylinders	5
Fuel type	Diesel
Consumption city	22.8 mpg
Consumption extra urban	36.2 mpg
Consumption combined	29.7 mpg
CO2 emission	275 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-10-08
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-05
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	30
Total items failed	0

MOT #13 2021-04-08 12:03

MOT test number 675014973569

Result ✓ Passed

Next expiry date 2022-04-20

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12**

2021-04-07 15:18

**MOT test number**

782507273342

**Result****✗ Failed**

- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11**

2020-04-21 14:39

**MOT test number**

339417494686

**Result****✓ Passed****MOT #10**

2019-05-28 11:49

**MOT test number**

702411039788

**Result****✓ Passed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Park brake travel has little reserve travel

**MOT #9** 2018-06-08 09:43**MOT test number** 927046726795**Result** ✓ Passed**Advice** Park brake lever has little reserve travel**MOT #8** 2017-06-06 15:25**MOT test number** 469891819852**Result** ✓ Passed**MOT #7** 2016-06-09 15:08**MOT test number** 772954675381**Result** ✓ Passed**MOT #6** 2015-06-11 16:09**MOT test number** 935962865151**Result** ✓ Passed**MOT #5** 2014-06-10 15:35**MOT test number** 508651364156**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside rear tyre starting to crack and split**MOT #4** 2013-06-07 10:01**MOT test number** 675278953125**Result** ✓ Passed



MOT #3	2012-06-12 08:52
MOT test number	988954862197
Result	✓ Passed

MOT #2	2011-05-17 12:10
MOT test number	396707131162
Result	✓ Passed
<div>Notice Child seat fitted not allowing full inspection of adult belt</div>	

MOT #1	2010-05-26 11:02
MOT test number	623066840113
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
5 September 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	5 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	M
<b>Single payment (12 months)</b>	£ 695,00,-
<b>Single six month payment</b>	£ 382,25,-
<b>Total payable by 12 monthly instalments</b>	£ 729,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>GR07DDX</b>
Plate since	2024-03-29
Current registration	 <b>GR07DDX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-06-11
Last registration	2021-04-08
Complete history	<a href="#">See info</a>



Registration #1	2007-06-11	13 mi
Registration #2	2010-05-26	41.291 mi
Registration #3	2011-05-17	55.461 mi
Registration #4	2012-06-12	71.119 mi
Registration #5	2013-06-07	83.853 mi
Registration #6	2014-06-10	95.249 mi
Registration #7	2015-06-11	104.703 mi
Registration #8	2016-06-09	111.388 mi
Registration #9	2016-06-09	111.388 mi
Registration #10	2016-06-09	111.388 mi
Registration #11	2016-06-09	111.388 mi
Registration #12	2016-06-09	111.388 mi
Registration #13	2016-06-09	111.388 mi
Registration #14	2016-06-09	111.388 mi
Registration #15	2016-06-09	111.388 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2230 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	BPE 011134