



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Grey
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-04-19
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-25
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	6
Total items failed	4

MOT #13	2024-04-10 08:32
MOT test number	935817945748
Result	✓ Passed
Next expiry date	2025-04-25

MOT #12	2023-04-17 15:04
MOT test number	487278482628
Result	✓ Passed

MOT #11	2022-04-26 23:46
MOT test number	138241402238
Result	✓ Passed

MOT #10	2022-04-26 23:46
MOT test number	373582060655
Result	✗ Failed
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Pass with rectification	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #9** 2021-07-28 09:44**MOT test number** 175458385820**Result** ✓ Passed**MOT #8** 2020-08-26 16:39**MOT test number** 429408578159**Result** ✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #7 2019-09-03 13:41**MOT test number** 106095213261**Result** ✓ Passed**MOT #6** 2018-07-19 14:14**MOT test number** 273742489352**Result** ✓ Passed**MOT #5** 2018-07-19 08:07**MOT test number** 410505344387**Result** ✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #4 2017-07-03 11:58**MOT test number** 550013709558**Result** ✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Tyre worn on inner edge

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #3	2016-06-30 15:47
MOT test number	884111317505
Result	✓ Passed

MOT #2	2015-07-27 15:59
MOT test number	595078305264
Result	✓ Passed

MOT #1	2014-06-20 10:42
MOT test number	366071774111
Result	✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
25 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	25 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	PF11AKZ
Plate since	2019-09-29
Current registration	PF11AKZ
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-07-28
Last registration	2024-04-10
Complete history	See info



Registration #1	2011-07-28	29 mi
Registration #2	2014-06-20	20.747 mi
Registration #3	2015-07-27	26.400 mi
Registration #4	2016-06-30	31.538 mi
Registration #5	2017-07-03	36.258 mi
Registration #6	2018-07-19	40.839 mi
Registration #7	2018-07-19	40.852 mi
Registration #8	2019-09-03	44.433 mi
Registration #9	2020-09-03	48.014 mi
Registration #10	2021-09-03	51.595 mi
Registration #11	2022-09-03	55.176 mi
Registration #12	2023-09-03	58.757 mi
Registration #13	2024-03-29	62.338 mi
Registration #14	2024-03-29	65.919 mi
Registration #15	2024-03-29	69.500 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1346 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1038586