



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN MATCH TDI
Colour	Silver
Year of manufacture	2009
Top speed	111 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	155 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-09-22
Pictures	36
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-11-27
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	32
Total items failed	19

MOT #14	2023-11-28 12:25
MOT test number	543087779790
Result	✓ Passed
Next expiry date	2024-11-27
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #13	2022-08-22 13:35
MOT test number	904821831068
Result	✓ Passed

MOT #12	2021-08-28 15:56
MOT test number	315792394605
Result	✓ Passed
Advice	Suspension arm corroded but not seriously weakened both rear trailing arms (5.3.3 (b) (i))
Minor	Front Suspension arm ball joint dust cover severely deteriorated both sides bottom ball joint (5.3.4 (b) (i))

**MOT #11**

2021-08-23 18:07

**MOT test number**

848464651707

**Result****✗ Failed**

- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))
- Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Front Suspension arm ball joint dust cover severely deteriorated both sides bottom ball joint (5.3.4 (b) (i))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Suspension arm corroded but not seriously weakened both rear trailing arms (5.3.3 (b) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Rear Coil spring fractured or broken both (5.3.1 (b) (i))

**MOT #10**

2019-04-27 10:07

**MOT test number**

116607529850

**Result****✓ Passed**

- Advice** Rear Anti-roll bar linkage ball joint has slight play both (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9** 2018-03-16 16:56**MOT test number** 910543984519**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2018-03-16 16:56**MOT test number** 883293042005**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #7** 2017-02-16 10:17**MOT test number** 751669139252**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Both sides (2.4.G.2)**Advice** Rear brake fluctuating, but not excessively Both sides (3.7.B.3)**MOT #6** 2016-02-19 12:22**MOT test number** 331361206843**Result** ✓ Passed**Advice** Unable to check underside fully due to covers**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5**

2015-02-20 10:02

**MOT test number**

558341955034

**Result**

✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Front wipers leaving small streak across windsreen but not affecting drivers view of the road
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4**

2015-02-11 10:59

**MOT test number**

415182745076

**Result**

✗ Failed

- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Notice** Nail in offside front tyre
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Offside rear tyre wearing on inside
- Pass with rectification** Offside Front Headlamp aim too low (1.8)
- Notice** Front wipers leaving small streak across windsreen but not affecting drivers view of the road
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Pass with rectification** Nearside Front Headlamp aim too low and too far to the left. (1.8)

**MOT #3**

2014-02-13 16:13

**MOT test number**

637864244093

**Result**

✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt



MOT #2	2014-02-10 11:56
MOT test number	717701244038
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Front Headlamp aim too high (1.8)
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Pass with rectification	Nearside Front Headlamp aim too high (1.8)
MOT #1	2012-10-25 11:14
MOT test number	625329992205
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
27 November 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	27 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>VN59VCX</b>
Plate since	2019-06-29
Current registration	<b>VN59VCX</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-12-18
Last registration	2023-11-28
Complete history	<a href="#">See info</a>



Registration #1	2009-12-18	16 mi
Registration #2	2012-10-25	20.448 mi
Registration #3	2014-02-10	29.544 mi
Registration #4	2014-02-13	29.625 mi
Registration #5	2015-02-11	38.133 mi
Registration #6	2015-02-20	38.279 mi
Registration #7	2016-02-19	48.257 mi
Registration #8	2017-02-16	59.177 mi
Registration #9	2018-02-16	69.177 mi
Registration #10	2019-02-16	79.177 mi
Registration #11	2020-02-16	89.177 mi
Registration #12	2021-02-16	99.177 mi
Registration #13	2022-02-16	109.177 mi
Registration #14	2023-02-16	119.177 mi
Registration #15	2024-02-16	129.177 mi
Registration #16	2025-02-16	139.177 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2678 mm
Kerb weight	2210 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BXE C57284