





report date: 2024-03-29

General information

Make	FORD
Model	FIESTA TITANIUM
Colour	Grey
Year of manufacture	-
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	128 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-05-26

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

2021-05-29 08:48

MOT test number 458960730075

Result \(\sqrt{Passed} \)

Next expiry date 2022-05-28

MOT #12 2021-05-28 14:15

MOT test number 739121573855

Result X Failed

Fail Fluid leak harmful to the environment or a risk to other road users Coolant (8.4.1 (a) (i))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #11 2020-07-24 14:12

MOT test number 319841094269

Result ✓ Passed

MOT #10 2020-07-24 09:50

MOT test number 537498626552

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #9 2019-07-26 08:54

MOT test number 795402404104

Result ✓ Passed

Advice Items removed from driver's view prior to test DEVICE HOLDER

CarCheck.co.uk page 3/12



MOT #8 2019-07-26 08:54

MOT test number 449944965736

Result X Failed

Pass with rectification Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Items removed from driver's view prior to test DEVICE HOLDER

Pass with rectification Offside Front Anti-roll bar linkage likely to become detached (5.3.3 (a) (ii))

MOT #7 2018-07-31 15:08

MOT test number 236309973123

Result
✓ Passed

Advice 1 I oil added

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Coolant level low

Advice Items removed from driver's view prior to test

Advice Road wheel slightly distorted all four (5.2.2 (c) (i))

MOT #6 2018-07-30 11:08

MOT test number 342858914228

Result × Failed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Items removed from driver's view prior to test

Fail Offside Front Drive shaft bearing excessively worn (6.1.7 (b) (i))

Advice Coolant level low

Advice Road wheel slightly distorted all four (5.2.2 (c) (i))

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

Advice 1 | oil added

CarCheck.co.uk page 4/12



MOT #5 2017-05-18 10:52

MOT test number 113001770325

Result ✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #4 2016-05-24 08:38

MOT test number 629979933753

Result ✓ Passed

MOT #3 2015-05-08 09:37

MOT test number 276148125132

Result ✓ Passed

Notice Offside front wheel bearing getting noisy when rotated

Advice Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2014-05-23 10:02

MOT test number 299513944495

Result

Passed

Advice Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

Advice Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

CarCheck.co.uk page 5/12



MOT #1 2013-05-17 12:07

MOT test number 728007033138

Result ✓ Passed

Advice Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Notice N/s sill at rear & n/s/r corner of bumper damaged

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner History	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NIE NIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-05-26
Last registration	2021-05-29
Complete history	See info



Registration #1	2010-05-26	15 mi
Registration #2	2013-05-17	24.346 mi
Registration #3	2014-05-23	34.625 mi
Registration #4	2015-05-08	42.313 mi
Registration #5	2016-05-24	50.709 mi
Registration #6	2017-05-18	56.143 mi
Registration #7	2018-07-30	64.148 mi
Registration #8	2018-07-31	64.148 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		0.00 44
Registration #15		0.777 66

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	42
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 9E63133