





report date: 2024-03-28

## General information

Make	VAUXHALL
Model	CROSSLAND ELITE NAV
Colour	Black
Year of manufacture	2018
Top speed	105 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	80 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.199 сс
Cylinders	3
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/12



# Internet history


## Entry 1

Date 2021-05-24

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



# MOT history

MOT expiry date	2024-05-17
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	23
Total items failed	2

MOT #5		2023-05-12 14:01
MOT test	number	380964037165
Result		<b>✓</b> Passed
Next expi	ry date	2024-05-17
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weake	ened (1.1.14 (a) (ii))
Advice	Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	=
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #4 2023-05-12 09:15

MOT test number 226835811657

Result × Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Advice Nearside Rear Inner Brake pad(s) wearing thin very close to limits (1.1.13 (a) (ii)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Rear Nail in tyre Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice **DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #3 2022-05-18 10:09

**MOT test number** 863646953921

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



MOT #2 2022-05-18 10:09

**MOT test number** 314205788426

Result X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

**Pass with rectification** Nearside Rear Position lamp adversely affected by the operation of another lamp stop lamp operating (4.2.3 (c))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

**Pass with rectification** Windscreen washer provides insufficient washer liquid both (3.5 (a))

**MOT #1** 2021-03-04 12:09

**MOT test number** 781608819297

**Result** ✓ Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	17 May 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28


## Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

### Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



### Extra VAUXHALL salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	history
O WILCI	,

Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	
*********	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
*********	
***************************************	
	More info >
Plate changes  See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-12
Last registration	2023-05-12
Complete history	See info



Registration #1	2018-03-12	14 mi
Registration #2	2021-03-04	20.157 mi
Registration #3		11.777 es
Registration #4	2022-05-18	29.885 mi
Registration #5		11.777 mi
Registration #6		11.777 es
Registration #7		11,777 es

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Adult	85%
Children	84%
Pedestrian	62%
Safety systems	57%
Overall rating	75%
Video	see crash video



# Dimensions & weight

Width	1976 mm
Height	1597 mm
Length	4212 mm
Wheel base	2604 mm
Kerb weight	1099 kg
Max. allowed weight	1690 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	10XVDA0035991 LEZ

CarCheck.co.uk page 12/12