



**EJ04VSX**

report date: 2024-03-29

General information

Make	FORD
Model	GALAXY GHIA TDDI
Colour	Gold
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	310 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg





Internet history

Entry 1

Date	2021-01-30
Pictures	3
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

<b>MOT #22</b>	2020-10-15 13:49
<b>MOT test number</b>	756399246294
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-10-14
<b>Advice</b>	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

<b>MOT #21</b>	2020-10-10 10:28
<b>MOT test number</b>	825115951209
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
<b>MAJOR</b>	Parking brake efficiency below requirements (1.4.2 (a) (i))
<b>MAJOR</b>	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
<b>Advice</b>	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

<b>MOT #20</b>	2019-05-31 12:32
<b>MOT test number</b>	149168071984
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
<b>Advice</b>	Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

**MOT #19**

2019-05-31 09:31

**MOT test number**

249159115102

**Result****✗ Failed****DANGEROUS** Front Brake disc in such a condition that it is seriously weakened both (1.1.14 (a) (ii))**Advice** Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**Advice** Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**MOT #18**

2018-06-01 10:45

**MOT test number**

710525894546

**Result****✓ Passed****Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #17**

2017-06-09 13:39

**MOT test number**

168356866889

**Result****✓ Passed**

**MOT #16** 2017-06-09 10:22**MOT test number** 833048199526**Result** ✗ Failed**Fail** Nearside Front Headlamp aim too high (1.8)**Fail** Nearside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #15** 2016-06-10 10:46**MOT test number** 691546051249**Result** ✓ Passed**MOT #14** 2015-06-08 11:58**MOT test number** 445679255124**Result** ✓ Passed**MOT #13** 2015-06-08 11:58**MOT test number** 105769155102**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #12** 2014-06-06 10:38**MOT test number** 825277554171**Result** ✓ Passed**MOT #11** 2014-06-06 10:38**MOT test number** 978407554108**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #10** 2013-05-31 10:24**MOT test number** 765891453170**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Front brake discs corrord on inner edge**MOT #9** 2012-06-01 13:16**MOT test number** 635023852189**Result** ✓ Passed**MOT #8** 2012-06-01 09:57**MOT test number** 326203152185**Result** ✗ Failed**Fail** Offside Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #7** 2011-06-06 16:15**MOT test number** 979027251145**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Child seats fitted to n/s/r n/s/c o/s/f o/s/r

**MOT #6** 2011-06-06 10:53**MOT test number** 107697051174**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Exhaust tailpipe not capable of allowing the emission probe to be inserted (7.4.B.1)**Fail** Exhaust has part of the system excessively deteriorated (7.1.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Child seats fitted to n/s/r n/s/c o/s/f o/s/r**MOT #5** 2010-06-02 12:09**MOT test number** 174223350108**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2010-06-02 12:09**MOT test number** 211143250148**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #3	2009-06-01 10:51
MOT test number	831342159167
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2008-06-02 10:52
MOT test number	301834758168
Result	✓ Passed

MOT #1	2007-06-02 11:30
MOT test number	273453157485
Result	✓ Passed





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EJ04VSX
Plate since	2019-03-29
Current registration	EJ04VSX
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-05-28
Last registration	2020-10-15
Complete history	<a href="#">See info</a>



Registration #1	2004-05-28	19 mi
Registration #2	2007-06-02	26.461 mi
Registration #3	2008-06-02	30.470 mi
Registration #4	2009-06-01	35.102 mi
Registration #5	2010-06-02	39.052 mi
Registration #6	2011-06-06	42.656 mi
Registration #7	2011-06-06	42.656 mi
Registration #8	2012-06-01	47.034 mi
Registration #9	2012-06-01	47.035 mi
Registration #10	2013-05-31	52.741 mi
Registration #11	2014-06-06	55.846 mi
Registration #12	2015-06-02	59.952 mi
Registration #13	2016-06-02	64.058 mi
Registration #14	2017-06-02	68.164 mi
Registration #15	2018-06-02	72.270 mi
Registration #16	2019-06-02	76.376 mi
Registration #17	2020-06-02	80.482 mi
Registration #18	2021-06-02	84.588 mi
Registration #19	2022-06-02	88.694 mi
Registration #20	2023-06-02	92.800 mi
Registration #21	2024-06-02	96.906 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2142 mm
Height	1759 mm
Length	4641 mm
Wheel base	2835 mm
Kerb weight	1694 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	3U31478