



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 T SE
Colour	Green
Year of manufacture	2006
Top speed	140 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	180 BHP
Max. torque	240 Nm at 5.300 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	39.8 mpg
Consumption combined	30.7 mpg
CO2 emission	212 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-09-07
Pictures	4
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-08-09
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #16	2023-08-04 15:18
MOT test number	971089113403
Result	✓ Passed
Next expiry date	2024-08-09

MOT #15	2023-08-04 09:49
MOT test number	357983561056
Result	✗ Failed
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Minor	Offside Front Tyre obviously under inflated (5.2.3 (l))

MOT #14	2022-08-04 10:06
MOT test number	655566269747
Result	✓ Passed
Advice	Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))
Advice	Child Seat fitted not allowing full inspection of adult belt nsr and osr
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Nail in tyre

**MOT #13** 2021-08-03 07:54**MOT test number** 523044251305**Result** ✓ Passed**MOT #12** 2020-08-04 10:00**MOT test number** 565094771680**Result** ✓ Passed**MOT #11** 2019-07-25 09:32**MOT test number** 235817849393**Result** ✓ Passed**MOT #10** 2018-07-25 10:26**MOT test number** 469735603861**Result** ✓ Passed**MOT #9** 2017-08-04 09:12**MOT test number** 799976819094**Result** ✓ Passed**MOT #8** 2016-08-10 10:34**MOT test number** 936809123692**Result** ✓ Passed**Advice** REAR TYRES STARTING TO PERISH**MOT #7** 2015-08-03 14:07**MOT test number** 195295815232**Result** ✓ Passed

**MOT #6** 2014-07-31 11:48**MOT test number** 917292914242**Result** ✓ Passed**Notice** Advanced corrosion exhaust system**Notice** Slight play front suspension lower arm bushes**MOT #5** 2013-08-01 13:31**MOT test number** 385513313202**Result** ✓ Passed**MOT #4** 2012-07-27 10:34**MOT test number** 797969302242**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #3** 2011-08-02 12:02**MOT test number** 309044511296**Result** ✓ Passed**MOT #2** 2010-07-26 08:00**MOT test number** 611367100261**Result** ✓ Passed**MOT #1** 2009-07-28 08:13**MOT test number** 340819809433**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	RN55PXJ
Plate since	2024-03-29
Current registration	RN55PXJ
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-02-22
Last registration	2023-08-04
Complete history	See info



Registration #1	2006-02-22	23 mi
Registration #2	2009-07-28	24.350 mi
Registration #3	2010-07-26	29.829 mi
Registration #4	2011-08-02	34.878 mi
Registration #5	2012-07-27	41.149 mi
Registration #6	2013-08-01	48.779 mi
Registration #7	2014-07-31	55.538 mi
Registration #8	2015-08-03	62.379 mi
Registration #9	2016-08-10	68.977 mi
Registration #10	2017-08-10	75.577 mi
Registration #11	2018-08-10	82.177 mi
Registration #12	2019-08-10	88.777 mi
Registration #13	2020-08-10	95.377 mi
Registration #14	2021-08-10	101.977 mi
Registration #15	2022-08-10	108.577 mi
Registration #16	2023-08-10	115.177 mi
Registration #17	2024-08-10	121.777 mi
Registration #18	2025-08-10	128.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1804 mm
Height	1428 mm
Length	4576 mm
Wheel base	2715 mm
Kerb weight	1427 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	3956903
---------------	---------