



HJ08YVP

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT CONNECT TDCI T230 L LWB P/V 90
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-30
Pictures	30
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-06
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	21
Total items failed	13

MOT #212023-09-04 16:19

MOT test number531915333359

Result✓ Passed

Next expiry date2024-09-06

- Advice**Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor**Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice**Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice**Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
- Advice**Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice**Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor**Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Minor**Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice**Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice**Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #20**

2023-09-04 16:19

MOT test number

101546301175

Result

✗ Failed

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #19

2022-08-19 17:07

MOT test number

671693624471

Result

✓ Passed

MOT #18

2021-09-07 11:45

MOT test number

423827234955

Result

✓ Passed

MOT #17

2021-08-31 16:31

MOT test number

879602932040

Result

✗ Failed

- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #16** 2020-12-01 15:19**MOT test number** 568510949120**Result** ✓ Passed**MOT #15** 2020-12-01 15:19**MOT test number** 598164189906**Result** ✗ Failed**Pass with rectification** Rear Stop lamp(s) all not working (4.3.1 (a) (iii))**MOT #14** 2019-03-25 11:53**MOT test number** 685278017150**Result** ✓ Passed**MOT #13** 2019-03-25 11:53**MOT test number** 578982522945**Result** ✗ Failed**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Stop lamp(s) not working high center (4.3.1 (a) (ii))**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #12** 2018-04-05 08:27**MOT test number** 956876860571**Result** ✓ Passed**MOT #11** 2018-04-05 08:27**MOT test number** 541480285667**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**MOT #10** 2017-03-17 09:46**MOT test number** 714722415359**Result** ✓ Passed**Advice** Offside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #9** 2016-03-11 11:17**MOT test number** 315378294765**Result** ✓ Passed**MOT #8** 2016-03-11 09:59**MOT test number** 343742714698**Result** ✗ Failed**Fail** Offside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #7** 2015-03-16 17:28**MOT test number** 585625175097**Result** ✓ Passed**MOT #6** 2015-03-16 17:28**MOT test number** 798785475064**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Pass with rectification** Offside Front Headlamp aim too far to the left (1.8)**MOT #5** 2014-03-20 16:30**MOT test number** 708179374068**Result** ✓ Passed



MOT #4	2013-03-16 11:46
---------------	------------------

MOT test number	427815573075
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2012-03-07 13:34
---------------	------------------

MOT test number	265437362031
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2012-03-06 10:54
---------------	------------------

MOT test number	809166562027
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Stop lamp not working (1.2.1b)
-------------	---

Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	---

Fail	Nearside Inner Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	--

MOT #1	2011-03-18 14:41
---------------	------------------

MOT test number	729527871084
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
6 September 2024

Tax status		Valid until 1 October
Days left		156
MOT expiry date		6 September 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-03-18
Last registration	2023-09-04
Complete history	See info



Registration #1	2008-03-18	15 mi
Registration #2	2011-03-18	21.047 mi
Registration #3	2012-03-06	30.540 mi
Registration #4	2012-03-07	30.550 mi
Registration #5	2013-03-16	38.825 mi
Registration #6	2014-03-20	46.310 mi
Registration #7	2015-03-16	54.989 mi
Registration #8	2016-03-11	64.300 mi
Registration #9	2016-03-11	64.300 mi
Registration #10	2017-03-17	68.285 mi
Registration #11	2018-04-05	72.161 mi
Registration #12	2019-03-20	75.277 mi
Registration #13	2019-03-20	75.277 mi
Registration #14	2019-03-20	75.277 mi
Registration #15	2019-03-20	75.277 mi
Registration #16	2019-03-20	75.277 mi
Registration #17	2019-03-20	75.277 mi
Registration #18	2019-03-20	75.277 mi
Registration #19	2019-03-20	75.277 mi
Registration #20	2019-03-20	75.277 mi
Registration #21	2019-03-20	75.277 mi
Registration #22	2019-03-20	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	601 mm
Length	4525 mm
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	8R08832