





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|-------------------|
| Model | TUCSON GDI SE NAV |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 113 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 130 BHP |
|-------------------------|---------------------|
| Max. torque | 132 Nm at 4.850 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 34.4 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 39.8 mpg |
| CO2 emission | 162 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/10



report date: 2024-03-28

Internet history

Entry 1

| Date | 2022-03-17 | |
|---------------|--------------------|--|
| Pictures | 1 | |
| Listing price | <u>View report</u> | |



source: cargurus.co.uk

CarCheck.co.uk page 2/10



BT68FLF report date: 2024-03-28

MOT history

| MOT expiry date | 2024-10-30 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 2 |
| Total items failed | 0 |

| MOT #3 | | 2023-10-26 11:13 |
|-----------|--|------------------|
| MOT test | number | 592395231254 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-10-30 |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #2 | 2022-10-28 08:18 |
|-----------------|------------------|
| MOT test number | 730330740485 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2021-10-13 08:29 |
| MOT test number | 792543812809 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/10



BT68FLF report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 306 |
| MOT expiry date | 30 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | 1 |
| First licence fee (12 months) | £ 645,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 4/10



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

BT68FLF

report date: 2024-03-28

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

See in this check if this HYUNDAI had different number plates.

More info >

More info >

CarCheck.co.uk page 7/10



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >


CarCheck.co.uk page 8/10



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 5 |
| First mileage registration | 2018-10-31 |
| Last registration | 2023-10-26 |
| Complete history | See info |



| Registration #1 | 2018-10-31 | 9 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-10-13 | 6.501 mi |
| Registration #3 | | 9.777 es |
| Registration #4 | | 71.777 66 |
| Registration #5 | | D.777 66 |

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 86% |
| Children | 85% |
| Pedestrian | 71% |
| Safety systems | 71% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 2065 mm |
|---------------------|---------|
| Height | 1650 mm |
| Length | 4475 mm |
| Wheel base | 2670 mm |
| Kerb weight | 1414 kg |
| Max. allowed weight | 2030 kg |

Additional information

| Fuel tank capacity | 62 l | |
|-----------------------------------|------------------|---------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 page | e 10/10 |