



HYUNDAI



report date: 2024-03-28

General information

|                     |                           |
|---------------------|---------------------------|
| Make                | HYUNDAI                   |
| Model               | I40 CRDI STYLE BLUE DRIVE |
| Colour              | White                     |
| Year of manufacture | 2012                      |
| Top speed           | 124 mph                   |
| 0 - 60 mph          | 10.6 seconds              |
| Gearbox             | 6 speed Manual            |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 134 BHP             |
| Max. torque             | 325 Nm at 2.500 rpm |
| Engine capacity         | 1.685 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 53.3 mpg            |
| Consumption extra urban | 68.9 mpg            |
| Consumption combined    | 62.8 mpg            |
| CO2 emission            | 119 g/km            |
| CO2 label               | C                   |



**MOT history**

|                           |            |
|---------------------------|------------|
| <b>MOT expiry date</b>    | 2021-11-02 |
| <b>MOT pass rate</b>      | 86 %       |
| <b>MOT passed</b>         | 6          |
| <b>Failed MOT tests</b>   | 1          |
| <b>Total advice items</b> | 5          |
| <b>Total items failed</b> | 1          |

|                         |   |
|-------------------------|---|
| <b>MOT #7</b>           | 2020-11-03 14:01  |
| <b>MOT test number</b>  | 962731399757  |
| <b>Result</b>           | ✓ Passed  |
| <b>Next expiry date</b> | 2021-11-02  |
| <b>Advice</b>           | Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))              |
| <b>Advice</b>           | Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) |

|                        |   |
|------------------------|---|
| <b>MOT #6</b>          | 2020-10-31 10:26  |
| <b>MOT test number</b> | 292040950201  |
| <b>Result</b>          | ✗ Failed  |
| <b>Fail</b>            | Offside Track rod end ball joint has excessive play (2.1.3 (b) (i)) |
| <b>Advice</b>          | Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))  |

|                        |                  |
|------------------------|------------------|
| <b>MOT #5</b>          | 2019-04-09 13:59 |
| <b>MOT test number</b> | 686100460520     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #4</b>          | 2018-05-05 10:02 |
| <b>MOT test number</b> | 744698613075     |
| <b>Result</b>          | ✓ Passed         |



|                 |  |
|-----------------|--|
| MOT #3          | 2017-04-27 12:47                                 |
| MOT test number | 669258518718                                     |
| Result          | ✓ Passed   |
| Advice          | Offside Rear Brake pad(s) wearing thin (3.5.1g)  |
| Advice          | Nearside Rear Brake pad(s) wearing thin (3.5.1g) |

|                 |                  |
|-----------------|------------------|
| MOT #2          | 2016-05-12 15:35 |
| MOT test number | 934461215025     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2015-08-18 09:34 |
| MOT test number | 369840735261     |
| Result          | ✓ Passed         |



Tax & MOT check

X

Untaxed

Tax expired:  
19 January 2021

X

MOT

Expired:  
2 November 2021

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 19 January 2021      |
| Days left        | 1196 days too late              |
| MOT expiry date  | 2 November 2021                 |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |                |
|---|----------------|
| Vehicle class                           | 49             |
| Band                                    | C              |
| Single payment (12 months)              | £ 35,00,-      |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,-      |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2019-01-01 |
| Current registration |            |
| Plate since          | 2019-01-01 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >





Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 8                        |
| First mileage registration | 2012-09-06               |
| Last registration          | 2020-11-03               |
| Complete history           | <a href="#">See info</a> |



|                 |            |           |
|-----------------|------------|-----------|
| Registration #1 | 2012-09-06 | 13 mi     |
| Registration #2 | 2015-08-18 | 32.762 mi |
| Registration #3 | 2016-05-12 | 39.644 mi |
| Registration #4 | 2017-04-27 | 50.844 mi |
| Registration #5 | 2019-05-20 | 55.277 mi |
| Registration #6 | 2019-05-20 | 55.277 mi |
| Registration #7 | 2019-05-20 | 55.277 mi |
| Registration #8 | 2019-05-20 | 55.277 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 92%                             |
| Children       | 86%                             |
| Pedestrian     | 43%                             |
| Safety systems | 86%                             |
| Overall rating | 80%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1815 mm |
| Height              | 1470 mm |
| Length              | 4770 mm |
| Wheel base          | 2770 mm |
| Kerb weight         | 1648 kg |
| Max. allowed weight | 2120 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 70 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |

|                        |              |
|------------------------|--------------|
| <b>Number of axles</b> | 2            |
| <b>Engine number</b>   | D4FDCU154091 |