



report date: 2024-03-28

General information

Make	FIAT
Model	500L POP STAR
Colour	Red
Year of manufacture	2017
Top speed	111 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-18
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	11
Total items failed	4

MOT #8	2023-06-19 07:53
MOT test number	105988605736
Result	✓ Passed
Next expiry date	2024-06-18
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7	2023-06-15 14:47
MOT test number	597502397322
Result	✗ Failed
Fail	Offside Front Lower Suspension arm pin or bush excessively worn inner rear (5.3.4 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #6** 2023-06-06 15:19**MOT test number** 844207683459**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear arm bush (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced Outer sill /  
damaged. Cut. (7.1.1 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn Rear arm bush (5.3.4 (a) (i))**MOT #5** 2022-05-26 15:11**MOT test number** 916847059911**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2021-06-07 15:11**MOT test number** 260054727418**Result** ✓ Passed**MOT #3** 2020-11-19 10:45**MOT test number** 289700384627**Result** ✓ Passed



MOT #2	2020-11-18 10:15
MOT test number	130587157694
Result	✗ Failed
Fail	Windscreen wiper does not clear the windscreen effectively os/ns (3.4 (b) (ii))

MOT #1	2020-02-20 09:09
MOT test number	953094707073
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
18 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	18 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>First licence fee (12 months)</b>	£ 255,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-05-08
Last registration	2023-06-19
Complete history	<a href="#">See info</a>



Registration #1	2017-05-08	13 mi
Registration #2	2020-02-20	10.245 mi
Registration #3	2020-11-18	11.151 mi
Registration #4	2020-11-19	11.152 mi
Registration #5	2020-05-20	10.245 mi
Registration #6	2020-05-20	10.245 mi
Registration #7	2020-05-20	10.245 mi
Registration #8	2020-05-20	10.245 mi
Registration #9	2020-05-20	10.245 mi
Registration #10	2020-05-20	10.245 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1784 mm
Height	1658 mm
Length	4242 mm
Wheel base	2612 mm
Kerb weight	1245 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	4115821