





report date: 2024-03-29

### General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Silver
Year of manufacture	2009
Top speed	101 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	78 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

### Internet history

#### Entry 1

Date 2021-08-27

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

## MOT history

MOT expiry date	2024-08-03
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #15		2023-07-27 13:51
MOT test	number	531651033520
Result		✓ Passed
Next exp	iry date	2024-08-03
Advice top strut r	Offside Front Upper Macpherson strut pin or bush worn but not resultin mount (5.3.4 (a) (i))	g in excessive movement
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteri	orated (5.3.4 (b) (i))
Advice	Central Rear Lower Engine mounting damaged but not to excess (6.1.8	(a) (i))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely dete	eriorated (5.3.4 (b) (i))

MOT #14	2022-08-04 11:14
---------	------------------

**MOT test number** 277258247608

**Result** ✓ Passed

Advice Rear Suspension component mounting prescribed area is corroded but not considered excessive Both Sides (5.3.6 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #13 2022-08-04 10:48

**MOT test number** 705943250500

**Result** X Failed

Advice Rear Suspension component mounting prescribed area is corroded but not considered excessive Both Sides (5.3.6 (a) (i))

Fail Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #12 2021-06-29 09:19

**MOT test number** 387485493632

**Result** ✓ Passed

**MOT #11** 2020-07-29 10:45

**MOT test number** 904407412614

**Result** 
✓ Passed

**MOT #10** 2019-07-12 15:03

**MOT test number** 761723446239

MOT #9 2019-07-06 10:41

MOT test number 101282916402

Result × Failed

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #8 2019-01-09 09:18

**MOT test number** 472004040988

**Result** ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #7	2018-01-12 09:13
MOT test number	317767493719
Result	✓ Passed
Advice Rear exhaust hanger weak	
real samuas nanger weak	
MOT #6	2017-01-10 11:34
MOT test number	145031195340
Result	✓ Passed
MOT #5	2016-01-09 09:32
MOT test number	429030920982
Result	✓ Passed
NOT #4	2014 12 20 10 20
MOT #4 MOT test number	2014-12-29 10:39
	719333164375
Result	<b>✓</b> Passed
MOT #3	2014-01-11 11:48
MOT test number	855651414038
Result	
MOT #2	2013-01-07 14:37
MOT test number	528027803001
Result	✓ Passed
MOT #1	2012-01-07 09:38
MOT test number	278817902091
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice All tyres cracking	

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	3 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

$\sim$	vner	L :	-4-	
- DV	vnar	nı	crc	T ( )

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	
THE PARTY OF THE P	
***************************************	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-01-13
Last registration	2023-07-27
Complete history	See info



Registration #1	2009-01-13	12 mi
Registration #2	2012-01-07	34.067 mi
Registration #3	2013-01-07	39.514 mi
Registration #4	2014-01-11	44.440 mi
Registration #5	2014-12-29	50.745 mi
Registration #6	2016-01-09	56.752 mi
Registration #7	2017-01-10	61.747 mi
Registration #8	2018-01-12	67.749 mi
Registration #9	2019-01-09	72.809 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		11.177 mi
Registration #14		
Registration #15		11.777 mi
Registration #15 Registration #16		71.777 mg

More info >

CarCheck.co.uk page 11/12



AG58MXU report date: 2024-03-29

Car features

S0225	Air conditionir
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1161 kg
Max. allowed weight	1605 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 8G06446