



General information

Make	VOLKSWAGEN
Model	TOURAN MATCH TDI
Colour	Red
Year of manufacture	2010
Top speed	111 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-11-20
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-16
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	46
Total items failed	1

MOT #16	2023-10-17 11:56
MOT test number	932987507127
Result	✓ Passed
Next expiry date	2024-10-16
Advice	Rear Coil spring corroded both rear (5.3.1 (b) (i))

MOT #15	2023-10-17 05:43
MOT test number	256789421006
Result	✗ Failed
MAJOR	Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords both rear core expose (5.2.3 (d) (i))
Advice	Rear Coil spring corroded both rear (5.3.1 (b) (i))
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #14	2022-10-07 11:22
MOT test number	537889682280
Result	✓ Passed
Advice	Rear Inner Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2021-10-06 13:59

MOT test number

874110699689

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**MOT #12**

2021-10-06 08:35

MOT test number

678664422924

Result

✗ Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**MOT #11**

2020-10-16 12:24

MOT test number

852468596614

Result

✓ Passed

Advice Slight smearing to windscreen**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Slight distortion to both headlamp aim**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Slight undulation to both rear tyre treads**Advice** Tyre slightly damaged/cracking or perishing And both are wearing on edges (5.2.3 (d) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #10**

2020-10-15 09:27

MOT test number

345273799908

Result**✗ Failed**

- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Tyre slightly damaged/cracking or perishing And both are wearing on edges (5.2.3 (d) (ii))
- MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Advice** Slight smearing to windscreen
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Slight distortion to both headlamp aim
- Advice** Slight undulation to both rear tyre treads

MOT #9

2019-06-24 15:46

MOT test number

661420467277

Result**✓ Passed**

- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush splitting (5.3.4 (a) (i))
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush splitting (5.3.4 (a) (i))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #8** 2019-06-24 08:12**MOT test number** 116112507648**Result** ✗ Failed

MAJOR Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush splitting (5.3.4 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush splitting (5.3.4 (a) (i))

MOT #7 2018-06-25 08:21**MOT test number** 236094623526**Result** ✓ Passed

Advice Nearside Slight smearing to windscreen

MOT #6 2017-06-26 11:23**MOT test number** 573129784439**Result** ✓ Passed

Advice Offside Front Tyre wearing on edges

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5 2016-06-16 16:08**MOT test number** 762710747508**Result** ✓ Passed



MOT #4	2016-06-16 09:37
MOT test number	637305235679
Result	✗ Failed
Fail	Nearside Front Tyre has ply or cords exposed Sidewall (4.1.D.1b)

MOT #3	2015-06-17 11:17
MOT test number	578098865176
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Cracks in both rear tyre treads
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Uneven front tyre wear

MOT #2	2014-05-28 08:38
MOT test number	257868744100
Result	✓ Passed

MOT #1	2013-05-22 12:01
MOT test number	145782943191
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
16 October 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	16 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 EJ10USS
Plate since	2019-06-29
Current registration	 EJ10USS
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-21
Last registration	2023-10-17
Complete history	See info



Registration #1	2010-06-21	20 mi
Registration #2	2013-05-22	7.939 mi
Registration #3	2014-05-28	9.594 mi
Registration #4	2015-06-17	17.306 mi
Registration #5	2016-06-16	23.744 mi
Registration #6	2016-06-16	23.744 mi
Registration #7	2017-06-26	32.858 mi
Registration #8	2018-06-25	40.976 mi
Registration #9	2019-06-24	49.310 mi
Registration #10	2020-06-23	55.377 mi
Registration #11	2020-06-23	55.377 mi
Registration #12	2020-06-23	55.377 mi
Registration #13	2020-06-23	55.377 mi
Registration #14	2020-06-23	55.377 mi
Registration #15	2020-06-23	55.377 mi
Registration #16	2020-06-23	55.377 mi
Registration #17	2020-06-23	55.377 mi
Registration #18	2023-10-17	55.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2678 mm
Kerb weight	2210 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BXE C99289