



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF GTD TDI
Colour	Blue
Year of manufacture	2018
Top speed	144 mph
0 - 100 km/h	7.5 seconds
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	135 kW / 184 HP / 181 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	125 g/km
CO2 label	D





## Internet history

### Entry 3

Date	2021-07-26
Pictures	8
Listing price	<a href="#">View report</a>



source: yesauto.com

### Entry 2


Date	2021-07-21
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

### Entry 1

Date	2021-07-17
Pictures	10
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-07-05
<b>MOT pass rate</b>	75 %
<b>MOT passed</b>	3
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	7
<b>Total items failed</b>	0

<b>MOT #4</b>	2023-07-06 07:53
<b>MOT test number</b>	598032782110
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-07-05

<b>MOT #3</b>	2022-07-06 13:10
<b>MOT test number</b>	191678057811
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #2</b>	2021-07-06 07:51
<b>MOT test number</b>	394160916980
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #1	2021-06-29 13:38
MOT test number	728259122220
Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
5 July 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	5 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>First licence fee (12 months)</b>	£ 210,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 255,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>CX18YVD</b>
Plate since	2019-03-29
Current registration	 <b>CX18YVD</b>
Plate since	2019-03-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-06-29
Last registration	2023-07-06
Complete history	<a href="#">See info</a>



Registration #1	2018-06-29	7 mi
Registration #2	2021-06-29	44.510 mi
Registration #3	2021-07-06	44.510 mi
Registration #4	2022-06-29	44.510 mi
Registration #5	2022-06-29	44.510 mi
Registration #6	2022-06-29	44.510 mi
Registration #7	2022-06-29	44.510 mi
Registration #8	2023-07-06	44.510 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	89%
Pedestrian	65%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2027 mm
Height	1482 mm
Length	4268 mm
Wheel base	2626 mm
Kerb weight	1377 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	DGCA206008