



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 SE LUX D S40
Colour	Grey
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-02
Pictures	22
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-10-04
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	34
Total items failed	10

MOT #16	2022-10-05 16:55
---------	------------------

MOT test number	507190546032
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-10-04
------------------	------------

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))
- Advice** Exhaust system corroded
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))

**MOT #15**

2022-10-04 08:29

MOT test number

800353508617

Result**✗ Failed****Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))**Advice** Exhaust system corroded**MOT #14**

2021-09-29 11:23

MOT test number

230512664690

Result**✓ Passed****MOT #13**

2021-09-22 15:03

MOT test number

194675990026

Result**✗ Failed****Fail** Offside Rear Brake lever has restricted free movement caliper (1.1.15 (e))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Nearside Front Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**Fail** Offside Rear Brake cable has restricted free movement (1.1.15 (e))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #12**

2020-09-03 13:38

MOT test number

435420533007

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front wishbone bushes worn and splitting

MOT #11

2020-09-03 11:15

MOT test number

686816951534

Result

✗ Failed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front wishbone bushes worn and splitting
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #10

2019-09-16 12:26

MOT test number

101999515716

Result

✓ Passed

- Advice** Front number plate deteriorated

**MOT #9** 2018-09-11 10:55**MOT test number** 581426638728**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2017-09-15 11:00**MOT test number** 618174557954**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #7** 2016-08-31 10:42**MOT test number** 960490359791**Result** ✓ Passed**Advice** Exhaust silencer corroded**Advice** Rear Brake pad(s) wearing thin 70-80% worn (3.5.1g)**MOT #6** 2015-09-10 11:27**MOT test number** 923784448797**Result** ✓ Passed**MOT #5** 2014-09-19 09:24**MOT test number** 946492064246**Result** ✓ Passed**Notice** Both front tyres worn on inner edge**Notice** Exhaust back box corroded

**MOT #4** 2013-09-02 16:30**MOT test number** 948115043294**Result** ✓ Passed**Notice** Exhaust back box corroded**MOT #3** 2012-09-14 11:29**MOT test number** 245258352213**Result** ✓ Passed**MOT #2** 2011-09-06 15:23**MOT test number** 959669541253**Result** ✓ Passed**MOT #1** 2011-09-06 11:28**MOT test number** 649349141209**Result** ✗ Failed**Notice** Both headlamps have poor output**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	RV58VWB
Plate since	2024-03-29
Current registration	RV58VWB
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-16
Last registration	2022-10-05
Complete history	See info



Registration #1	2008-09-16	22 mi
Registration #2	2011-09-06	42.532 mi
Registration #3	2011-09-06	42.533 mi
Registration #4	2012-09-14	67.287 mi
Registration #5	2013-09-02	77.870 mi
Registration #6	2014-09-19	88.480 mi
Registration #7	2015-09-10	99.930 mi
Registration #8	2016-08-31	110.708 mi
Registration #9	2017-09-15	121.063 mi
Registration #10	2018-09-02	131.877 mi
Registration #11	2019-09-02	142.877 mi
Registration #12	2020-09-02	153.877 mi
Registration #13	2021-09-02	164.877 mi
Registration #14	2022-09-02	175.877 mi
Registration #15	2023-09-02	186.877 mi
Registration #16	2024-09-02	197.877 mi
Registration #17	2025-09-02	208.877 mi
Registration #18	2026-09-02	219.877 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	411629