



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE LUX
Colour	Black
Year of manufacture	2015
Top speed	137 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic


Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G



**Internet history****Entry 5**

Date	2023-03-18
Pictures	12
Listing price	View report

source: [cargurus.co.uk](https://www.cargurus.co.uk)**Entry 4**


Date	2022-12-30
Pictures	0
Listing price	View report

source: [cargurus.co.uk](https://www.cargurus.co.uk)**Entry 3**

Date	2022-12-29
Pictures	0
Listing price	View report

source: [autotrader.co.uk](https://www.autotrader.co.uk)**Entry 2**

Date	2021-08-10
Pictures	36
Listing price	View report

source: [cargurus.co.uk](https://www.cargurus.co.uk)**Entry 1**

CarCheck.co.uk

Date	2021-08-08
Pictures	36
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-26
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	15
Total items failed	1

MOT #11	2024-03-20 16:14
MOT test number	424708445156
Result	✓ Passed
Next expiry date	2025-03-26
Advice	Offside Rear Nail in tyre
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords deepish cut in tread (5.2.3 (d) (i))

MOT #10	2024-03-20 13:44
MOT test number	464321864288
Result	✗ Failed
MAJOR	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
MAJOR	Power steering component leaking unable to fully access areas as engine undertray fitted underside of vehicle wet with oil and leaking (2.1.5 (a))
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Offside Rear Nail in tyre
MAJOR	Power steering fluid reservoir empty (2.1.5 (b) (ii))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords deepish cut in tread (5.2.3 (d) (i))
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #9** 2023-03-27 15:08**MOT test number** 976098535134**Result** ✓ Passed**MOT #8** 2022-08-12 14:40**MOT test number** 721814787935**Result** ✓ Passed**MOT #7** 2021-08-20 16:46**MOT test number** 844261857874**Result** ✓ Passed**MOT #6** 2021-04-15 15:53**MOT test number** 779413990007**Result** ✓ Passed**MOT #5** 2021-04-13 12:27**MOT test number** 587736175285**Result** ✗ Failed**MAJOR** Windscreen washer not working (3.5 (a))**MOT #4** 2020-04-14 11:11**MOT test number** 147196001328**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing outer wall (5.2.3 (d) (ii))**Advice** Nearside Rear Nail in tyre

**MOT #3** 2020-04-14 11:11**MOT test number** 300987004249**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing outer wall (5.2.3 (d) (ii))**Pass with rectification** Headlamp aim too high BOTH (4.1.2 (a))**MOT #2** 2019-03-28 16:40**MOT test number** 460470162776**Result** ✓ Passed**MOT #1** 2018-03-09 11:04**MOT test number** 840870078891**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
26 March 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	26 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KN15VZM
Plate since	2015-05-29
Current registration	KN15VZM
Plate since	2015-05-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2015-03-31
Last registration	2024-03-20
Complete history	See info



Registration #1	2015-03-31	10 mi
Registration #2	2018-03-09	33.450 mi
Registration #3	2019-03-28	40.619 mi
Registration #4	2020-04-14	46.324 mi
Registration #5	2020-04-14	46.324 mi
Registration #6	2021-04-13	50.623 mi
Registration #7	2021-04-15	50.659 mi
Registration #8	2022-03-20	55.277 mi
Registration #9	2022-03-20	55.277 mi
Registration #10	2022-03-20	55.277 mi
Registration #11	2022-03-20	55.277 mi
Registration #12	2022-03-20	55.277 mi
Registration #13	2022-03-20	55.277 mi
Registration #14	2022-03-20	55.277 mi
Registration #15	2022-03-20	55.277 mi
Registration #16	2022-03-20	55.277 mi
Registration #17	2022-03-20	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2106 mm
Height	1547 mm
Length	4814 mm
Wheel base	2816 mm
Kerb weight	1769 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1559733