



report date: 2024-03-28

General information

Make	KIA
Model	CARENS GS CRDI
Colour	Black
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	45.6 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-21
Pictures	18
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #18	2023-04-06 07:29
MOT test number	365270157112
Result	✓ Passed
Next expiry date	2024-04-05
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2023-04-06 07:29
MOT test number	631075961266
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #16	2022-03-07 15:34
MOT test number	326042724482
Result	✓ Passed
Advice	Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15	2021-02-22 11:59
MOT test number	380131476739
Result	✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracked in tread grooves (5.2.3 (d) (ii))

Minor Windscreen damaged but not adversely affecting driver's view chip in zone B (3.2 (a) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Minor Windscreen damaged but not adversely affecting driver's view crack in n/s lower corner of windscreen in painted area (3.2 (a) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #14**

2021-02-22 10:00

MOT test number

848167490858

Result**✗ Failed****Minor** Windscreen damaged but not adversely affecting driver's view chip in zone B (3.2 (a) (i))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracked in tread grooves (5.2.3 (d) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view crack in n/s lower corner of windscreen in painted area (3.2 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13**

2020-02-24 09:24

MOT test number

847452839833

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge Bald on edges, inner edge almost worn to cords (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Items removed from driver's view prior to test**Minor** Nearside Windscreen damaged but not adversely affecting driver's view Small chip (3.2 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened Inner face (1.1.14 (a) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Inner face (1.1.14 (a) (ii))

**MOT #12** 2019-03-13 08:59**MOT test number** 979467293004**Result** ✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread Damaged (0.1 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Bald on inner edge (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material All metal brake pipes greased (1.1.11 (c))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Items removed from driver's view prior to test
- Minor** Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #11 2019-03-12 17:09**MOT test number** 935927823772**Result** ✗ Failed

- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Towbar attachment insecure Sockets (6.1.6 (c) (i))
- Minor** Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material All metal brake pipes greased (1.1.11 (c))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Bald on inner edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread Damaged (0.1 (b))

MOT #10 2018-03-13 16:45**MOT test number** 418795440059**Result** ✓ Passed

**MOT #9** 2018-03-13 15:08**MOT test number** 916811946023**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #8** 2017-03-02 11:51**MOT test number** 963164662805**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #7** 2016-03-03 14:23**MOT test number** 972764995954**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Tyre worn close to the legal limit worn on inner edge (4.1.E.1)

**MOT #6**

2016-03-03 12:48

MOT test number

755459390401

Result

✗ Failed

- Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Rear Tyre worn close to the legal limit worn on inner edge (4.1.E.1)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #5

2015-03-06 12:40

MOT test number

866585865032

Result

✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #4

2014-03-06 14:57

MOT test number

346745764080

Result

✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components



MOT #3 2013-03-19 16:58

MOT test number 126428673463

Result ✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2012-03-02 14:46

MOT test number 276832062095

Result ✓ Passed

Notice Nail in nearside rear tyre

MOT #1 2012-03-02 14:46

MOT test number 918012662098

Result ✗ Failed

Pass with rectification Offside Front Headlamp aim too high (1.8)

Notice Nail in nearside rear tyre



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	YG09CYF
Plate since	2024-03-28
Current registration	YG09CYF
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-01
Last registration	2023-04-06
Complete history	See info



Registration #1	2009-03-01	14 mi
Registration #2	2012-03-02	28.164 mi
Registration #3	2013-03-19	40.351 mi
Registration #4	2014-03-06	50.703 mi
Registration #5	2015-03-06	56.741 mi
Registration #6	2016-03-03	61.586 mi
Registration #7	2016-03-03	61.586 mi
Registration #8	2017-03-02	65.446 mi
Registration #9	2018-03-13	69.034 mi
Registration #10	2018-03-13	69.034 mi
Registration #11	2019-03-01	75.000 mi
Registration #12	2019-03-01	75.000 mi
Registration #13	2019-03-01	75.000 mi
Registration #14	2019-03-01	75.000 mi
Registration #15	2019-03-01	75.000 mi
Registration #16	2019-03-01	75.000 mi
Registration #17	2019-03-01	75.000 mi
Registration #18	2019-03-01	75.000 mi
Registration #19	2019-03-01	75.000 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1631 kg
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

D4EA7H338275