



report date: 2024-03-28

General information

Make	BMW
Model	X3 D SE
Colour	Black
Year of manufacture	2007
Top speed	123 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	330 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	191 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-06-12
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-23
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	50
Total items failed	22

MOT #24	2024-02-23 12:11
MOT test number	336146543571
Result	✓ Passed
Next expiry date	2025-02-23

MOT #23	2024-02-23 11:25
MOT test number	481218438104
Result	✗ Failed
Fail	Offside Front Road wheel fixing missing (5.2.1 (a) (i))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #22	2023-02-24 13:01
MOT test number	122442214390
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21**

2022-02-23 16:55

MOT test number

342367347254

Result

✓ Passed

Advice Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Park brake 19%**MOT #20**

2022-02-23 16:55

MOT test number

114386299025

Result

✗ Failed

Advice Park brake 19%**Pass with rectification** Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #19**

2021-02-23 15:12

MOT test number

887945286843

Result

✓ Passed

Advice Lower vehicle has under trays obscuring some inspections,advise**Advice** Rear Tyre slightly damaged osr and nsr tyres inner edges worn,advise (5.2.3 (d) (ii))**Advice** Rear wiper rubber split,advise**Advice** Offside Front wheel backing plate loose,advise**Advice** Brake hose has slight corrosion to ferrule osf,nsf,osr,nsr,advise (1.1.12 (f) (i))

**MOT #18**

2021-02-23 11:38

MOT test number

174717601435

Result**✗ Failed**

- Advice** Offside Front wheel backing plate loose,advise
- Fail** Central Lower Exhaust diesel particulate filter shows evidence of tampering. (8.2.2.1 (c))
- Advice** Brake hose has slight corrosion to ferrule osf,nsf,osr,nsr,advise (1.1.12 (f) (i))
- Advice** Lower vehicle has under trays obscuring some inspections,advise
- Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Fail** Rear Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Rear Tyre slightly damaged osr and nsr tyres inner edges worn,advise (5.2.3 (d) (ii))
- Advice** Rear wiper rubber split,advise

MOT #17

2021-02-19 15:14

MOT test number

670710068487

Result**✗ Failed**

- Advice** The offside handbrake effort is very low compared to the nearside
- Fail** Emissions not tested (8.2.2.2 (e))
- Advice** The central tread on both rear tyres is getting very low
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #16**

2021-02-01 13:37

MOT test number

749014360864

Result**✗ Failed**

- Advice** The central tread on both rear tyres is very low
- Fail** Offside Headlamp levelling device inoperative (4.1.5 (a))
- Advice** The offside parking brake effort is very low
- Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Advice** The oil level did not register on the dipstick before the test
- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Side repeater likely to become detached (4.4.1 (c) (ii))

MOT #15

2020-02-06 10:10

MOT test number

301351620399

Result**✓ Passed**

- Advice** Rear Coil spring worn both (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Rear Shock absorbers light misting of oil or has limited damping effect both damping reduced (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #14**

2020-02-05 10:13

MOT test number

495664109541

Result

✗ Failed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Rear Shock absorbers light misting of oil or has limited damping effect both damping reduced (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #13

2019-02-05 16:42

MOT test number

569877567518

Result

✓ Passed

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources advise (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge worn excessively,advise (5.2.3 (e))
- Advice** Rear no emissions detected,advise
- Advice** Rear Lower Sub-frame corroded but not seriously weakened and rear axle,advise (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge worn excessively,advise (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt advise

**MOT #12**

2019-02-05 10:36

MOT test number

670564608305

Result**✗ Failed****Advice**

Offside Front Tyre worn close to legal limit/worn on edge inner edge worn excessively,advise (5.2.3 (e))

Fail

Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail

Offside Rear Tyre tread depth below requirements of 1.6mm cracks in tread (5.2.3 (e))

Advice

Rear Lower Sub-frame corroded but not seriously weakened and rear axle,advise (5.3.3 (b) (i))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt advise

Advice

Nearside Front Tyre worn close to legal limit/worn on edge inner edge worn excessively,advise (5.2.3 (e))

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources advise (4.7.1 (b) (i))

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm cracks in tread (5.2.3 (e))

Fail

Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice

Rear no emissions detected,advise

MOT #11

2018-02-08 10:54

MOT test number

886529359694

Result**✓ Passed****Advice**

Under-trays fitted obscuring some underside components

MOT #10

2017-01-24 13:42

MOT test number

199573333753

Result**✓ Passed****MOT #9**

2016-01-14 13:53

MOT test number

750586900569

Result**✓ Passed**

**MOT #8** 2015-01-03 12:33**MOT test number** 649143805064**Result** ✓ Passed

- Notice** Front tyres wearing on edges
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components

MOT #7 2014-12-23 15:07**MOT test number** 956437654339**Result** ✗ Failed

- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front tyres wearing on edges
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components

MOT #6 2013-12-07 10:10**MOT test number** 465961543362**Result** ✓ Passed**MOT #5** 2013-11-18 15:00**MOT test number** 479942923337**Result** ✗ Failed

- Fail** Nearside Rear coil spring broken (2.4.C.1a)

MOT #4 2012-11-14 12:40**MOT test number** 797139912378**Result** ✓ Passed



MOT #3	2011-11-09 10:50
MOT test number	457753411368
Result	✓ Passed
MOT #2	2010-07-29 12:25
MOT test number	223240510256
Result	✓ Passed
MOT #1	2010-06-04 14:20
MOT test number	203675450192
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
23 February 2025

Tax status	Valid until 1 December
Days left	217
MOT expiry date	23 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-06-21
Last registration	2024-02-23
Complete history	See info



Registration #1	2007-06-21	14 mi
Registration #2	2010-06-04	45.946 mi
Registration #3	2010-07-29	46.269 mi
Registration #4	2011-11-09	56.289 mi
Registration #5	2012-11-14	62.649 mi
Registration #6	2013-11-18	74.643 mi
Registration #7	2013-12-07	74.997 mi
Registration #8	2014-12-23	81.571 mi
Registration #9	2015-01-03	81.704 mi
Registration #10	2016-01-14	92.546 mi
Registration #11	2017-01-24	103.169 mi
Registration #12	2018-02-08	110.686 mi
Registration #13	2019-02-05	124.397 mi
Registration #14	2020-03-20	131.377 mi
Registration #15	2020-03-20	131.377 mi
Registration #16	2020-03-20	131.377 mi
Registration #17	2020-03-20	131.377 mi
Registration #18	2020-03-20	131.377 mi
Registration #19	2020-03-20	131.377 mi
Registration #20	2020-03-20	131.377 mi
Registration #21	2020-03-20	131.377 mi
Registration #22	2020-03-20	131.377 mi
Registration #23	2020-03-20	131.377 mi
Registration #24	2020-03-20	131.377 mi
Registration #25	2020-03-20	131.377 mi
Registration #26	2024-02-23	131.377 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1853 mm
Height	1674 mm
Length	4569 mm
Wheel base	2795 mm
Kerb weight	1745 kg
Max. allowed weight	2265 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	81256543