



General information

Make	FORD
Model	MONDEO ZETEC 136PS
Colour	Grey
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	319 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-03
Pictures	8
Listing price	View report



source: cargurus.co.uk





MOT history

MOT expiry date	2024-11-13
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	20
Total items failed	6

MOT #15	2023-11-13 12:52
MOT test number	984437468391
Result	✓ Passed
Next expiry date	2024-11-13
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Engine cover under trays and sill covers fitted
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Front Brake pad(s) wearing thin inner pads look low (1.1.13 (a) (ii))
Advice	Corrosion to the suspension arms
Advice	Rear Suspension arm pin or bush worn but not resulting in excessive movement both the trailing arm front bushes (5.3.4 (a) (i))

**MOT #14**

2023-11-13 12:52

MOT test number

571629947123

Result

✗ Failed

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Corrosion to the suspension arms**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Pass with rectification** Offside Position lamp not working flashing (4.2.1 (a) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Front Brake pad(s) wearing thin inner pads look low (1.1.13 (a) (ii))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both the trailing arm front bushes (5.3.4 (a) (i))**Advice** Engine cover under trays and sill covers fitted**MOT #13**

2022-11-14 09:52

MOT test number

644390195083

Result

✓ Passed

Advice Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Tyre worn close to legal limit/worn on edge Nearside and Offside (5.2.3 (e))**Advice** Front Suspension arm corroded but not seriously weakened Nearside and Offside (5.3.3 (b) (i))**MOT #12**

2021-10-11 15:18

MOT test number

913016687238

Result

✓ Passed

MOT #11

2021-03-05 15:23

MOT test number

723321525459

Result

✓ Passed



MOT #10	2020-03-09 15:20
---------	------------------

MOT test number	187070412721
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #9	2020-03-09 13:40
--------	------------------

MOT test number	242303149389
-----------------	--------------

Result	✗ Failed
--------	----------

Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
-------------	---

MOT #8	2019-03-16 13:34
--------	------------------

MOT test number	775986626585
-----------------	--------------

Result	✓ Passed
--------	----------

Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
--------------	--

MOT #7	2018-02-26 16:41
--------	------------------

MOT test number	851804348162
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #6	2017-03-15 12:10
--------	------------------

MOT test number	129494254406
-----------------	--------------

Result	✓ Passed
--------	----------

Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

MOT #5	2016-03-11 14:46
--------	------------------

MOT test number	237480102076
-----------------	--------------

Result	✓ Passed
--------	----------

**MOT #4** 2016-03-11 14:46**MOT test number** 475670354535**Result** ✗ Failed**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Pass with rectification** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #3** 2015-03-12 14:30**MOT test number** 875371275034**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2014-03-13 15:28**MOT test number** 359972674095**Result** ✓ Passed**MOT #1** 2013-03-14 11:40**MOT test number** 817663273036**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
13 November 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	13 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-17
Last registration	2023-11-13
Complete history	See info



Registration #1	2010-03-17	22 mi
Registration #2	2013-03-14	42.320 mi
Registration #3	2014-03-13	51.205 mi
Registration #4	2015-03-12	67.165 mi
Registration #5	2016-03-11	77.036 mi
Registration #6	2016-03-11	77.036 mi
Registration #7	2017-03-15	97.983 mi
Registration #8	2018-02-26	113.011 mi
Registration #9	2019-03-16	118.641 mi
Registration #10	2020-03-20	121.277 mi
Registration #11	2020-03-20	121.277 mi
Registration #12	2020-03-20	121.277 mi
Registration #13	2020-03-20	121.277 mi
Registration #14	2020-03-20	121.277 mi
Registration #15	2020-03-20	121.277 mi
Registration #16	2020-03-20	121.277 mi
Registration #17	2020-03-20	121.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

AB89987