





report date: 2024-03-28

#### General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Black
Year of manufacture	2008
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/11



EA58VPF
report date: 2024-03-28

MOT history

MOT expiry date	2021-11-04
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	23
Total items failed	2

MOT #12		2020-10-30 16:50
MOT test	number	863620563869
Result		✓ Passed
Next expi	ry date	2021-11-04
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Heat shield insecure	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #11		2019-11-04 15:15
MOT test	number	973086471331
Result		✓ Passed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 2/11



report date: 2024-03-28

**MOT #10** 2019-11-04 13:00

**MOT test number** 472502337229

**Result** X Failed

MAJOR Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MAJOR Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #9 2018-10-26 08:59

**MOT test number** 563253349392

**Result** ✓ Passed

MOT #8 2017-11-03 10:29

**MOT test number** 641069894317

Result / Passed

**Advice** Front tyres slightly perished

**Advice** Wipers slightly smear

MOT #7 2016-10-29 07:41

**MOT test number** 948262150430

Result \rightarrow Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #6		2015-10-30 12:17
MOT test	number	188212538033
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2014-10-13 09:00
MOT test number	228956684219
Result	✓ Passed
Advice Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2013-10-17 10:36
MOT test number	166960693253
Result	✓ Passed

MOT #3	2012-11-05 08:33
MOT test number	819050312300
Result	<b>✓</b> Passed

MOT #2	2012-10-29 09:10
MOT test number	498273902417
Result	<b>X</b> Failed
Fail Offside rear parking brake recording little or no effort (3.7.B.6a)	
Fail Parking brake: efficiency below requirements (3.7.B.7)	

MOT #1	2011-11-16 08:51
MOT test number	396520121355
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax expired: 11 November 2020

# X MOT

Expired: 4 November 2021

Tax status	Expired at 11 November 2020
Days left	1264 days too late
MOT expiry date	4 November 2021
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



EA58VPF
report date: 2024-03-28

Owner history

e union motory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-11-20
Last registration	2020-10-30
Complete history	See info



Registration #1	2008-11-20	13 mi
Registration #2	2011-11-16	22.582 mi
Registration #3	2012-10-29	27.013 mi
Registration #4	2012-11-05	27.298 mi
Registration #5	2013-10-17	31.187 mi
Registration #6	2014-10-13	34.847 mi
Registration #7	2015-10-30	36.356 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

## Additional information

Fuel tank capacity	53
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2
Engine number 8K23159