



RJ58NGY

report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Blue
Year of manufacture	2008
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





MOT history

MOT expiry date	2021-12-13
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	31
Total items failed	7

MOT #12	2020-12-14 16:41
MOT test number	267913890157
Result	✓ Passed
Next expiry date	2021-12-13

MOT #11	2018-05-01 09:12
MOT test number	115631925212
Result	✓ Passed

- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Oil leak
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides lipped (3.5.1i)
- Advice** Non obligatory mirror damaged

**MOT #10**

2018-04-28 09:09

MOT test number

146070827643

Result

✗ Failed

- Fail** Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Non obligatory mirror damaged
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Child Seat fitted not allowing full inspection of adult belt 2 fitted at rear
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides lipped (3.5.1i)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Oil leak

MOT #9

2017-02-28 11:57

MOT test number

168202996685

Result

✓ Passed

- Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #8

2016-02-01 15:41

MOT test number

373191305275

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit wearing unevenly, balding on inner edge/centre but not over 2/3 (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2016-02-01 15:41**MOT test number** 812372125706**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit wearing unevenly, balding on inner edge/centre but not over 2/3 (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2015-02-05 16:34**MOT test number** 827976535024**Result** ✓ Passed**MOT #5** 2014-08-21 12:57**MOT test number** 725123134242**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front/rear tyres wearing on edges**MOT #4** 2013-08-21 14:04**MOT test number** 605953033262**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #3** 2012-08-21 16:38**MOT test number** 769714732206**Result** ✓ Passed**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2011-08-25 14:29**MOT test number** 468557631249**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2011-08-25 11:15**MOT test number** 545997331288**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

X

Untaxed

Tax expired:
1 January 2021

X

MOT

Expired:
13 December 2021

Tax status	Expired at 1 January 2021
Days left	1214 days too late
MOT expiry date	13 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	RJ58NGY
Plate since	2019-03-28
Current registration	RJ58NGY
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-11-24
Last registration	2020-12-14
Complete history	See info



Registration #1	2008-11-24	9 mi
Registration #2	2011-08-25	103.630 mi
Registration #3	2011-08-25	103.635 mi
Registration #4	2012-08-21	118.999 mi
Registration #5	2013-08-21	146.780 mi
Registration #6	2014-08-21	155.171 mi
Registration #7	2015-02-05	157.958 mi
Registration #8	2016-05-20	161.277 mi
Registration #9	2017-05-20	161.277 mi
Registration #10	2018-05-20	161.277 mi
Registration #11	2019-05-20	161.277 mi
Registration #12	2020-05-20	161.277 mi
Registration #13	2021-05-20	161.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1457 mm
Length	4830 mm
Wheel base	2754 mm
Kerb weight	1590 kg
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8L50847