



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	E E350 CDI BLUEEFFICIENCY SPORT
Colour	Silver
Year of manufacture	2009
Top speed	155 mph
0 - 100 km/h	6.7 seconds
0 - 60 mph	6.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	170 kW / 232 HP / 231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I






## Internet history

### Entry 2

Date	2022-04-06
Pictures	8
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

### Entry 1

Date	2021-10-22
Pictures	6
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-04-12
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	37
Total items failed	11

MOT #17	2023-03-29 12:56
MOT test number	581609253939
Result	✓ Passed
Next expiry date	2024-04-12

MOT #16	2022-04-13 11:53
MOT test number	509064121716
Result	✓ Passed

MOT #15	2021-10-09 09:32
MOT test number	247738048841
Result	✓ Passed

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14	2021-03-20 10:35
MOT test number	144933926780
Result	✓ Passed



MOT #13

2020-03-25 14:44

MOT test number

106353666361

Result

✓ Passed

- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))
- Advice

Offside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))
- Advice

Coil spring corroded both rear (5.3.1 (b) (i))
- Advice

Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))
- Advice

Nearside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Rear subframe bushes worn/ weak

**MOT #12**

2020-03-24 17:25

**MOT test number**

692091710296

**Result****✗ Failed****Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))**Advice** Coil spring corroded both rear (5.3.1 (b) (i))**Advice** Rear subframe bushes worn/ weak**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))**MOT #11**

2019-03-13 11:47

**MOT test number**

938072924657

**Result****✓ Passed****Advice** Front both tyres worn inner shoulders

**MOT #10**

2019-03-08 09:59

**MOT test number**

405059993211

**Result**

✗ Failed

**Fail** Nearside Front Road wheel fixing missing bolt (5.2.1 (a) (i))**Advice** Front both tyres worn inner shoulders**Minor** Headlamp switch does not immediately illuminate all dipped beam headlamps switch not working (4.1.3 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge centre 2mm and cuts inner side wall (5.2.3 (e))**Fail** Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure side wall (5.2.3 (d) (ii))**Fail** Rear fog lamp tell-tale not working (4.9.1 (a) (ii))**MOT #9**

2017-11-17 11:47

**MOT test number**

416913592237

**Result**

✓ Passed

**Advice** Engine covers fitted**MOT #8**

2017-11-16 11:22

**MOT test number**

675397757147

**Result**

✗ Failed

**Advice** Engine covers fitted**Fail** Nearside Front Wheel bolt(s) missing (4.2.A.1e)**Fail** Nearside Headlamp aim too low (1.8)**MOT #7**

2016-11-05 10:48

**MOT test number**

840064117917

**Result**

✓ Passed

**MOT #6** 2016-11-05 10:48**MOT test number** 882562573482**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #5** 2015-11-06 17:49**MOT test number** 472646877559**Result** ✓ Passed**MOT #4** 2014-11-01 15:19**MOT test number** 417375304327**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #3** 2014-11-01 15:19**MOT test number** 758655604343**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #2** 2013-10-24 09:11**MOT test number** 597047593223**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2012-10-30 09:16
MOT test number	538894402342
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Under-trays fitted obscuring some underside components





Tax & MOT check

X

Untaxed

Tax expired:  
7 April 2024

X

MOT

Expired:  
12 April 2024

Tax status	Expired at 7 April 2024
Days left	23 days too late
MOT expiry date	12 April 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2023-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-06
Last registration	2023-03-29
Complete history	<a href="#">See info</a>



Registration #1	2009-11-06	25 mi
Registration #2	2012-10-30	46.878 mi
Registration #3	2013-10-24	55.393 mi
Registration #4	2014-11-01	65.364 mi
Registration #5	2015-11-06	70.112 mi
Registration #6	2016-11-05	75.697 mi
Registration #7	2016-11-05	75.697 mi
Registration #8	2017-11-16	86.075 mi
Registration #9	2017-11-17	86.075 mi
Registration #10	2019-03-08	100.601 mi
Registration #11	2019-03-08	100.601 mi
Registration #12	2019-03-08	100.601 mi
Registration #13	2019-03-08	100.601 mi
Registration #14	2019-03-08	100.601 mi
Registration #15	2019-03-08	100.601 mi
Registration #16	2019-03-08	100.601 mi
Registration #17	2019-03-08	100.601 mi
Registration #18	2019-03-08	100.601 mi
Registration #19	2019-03-08	100.601 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1786 mm
Height	1397 mm
Length	4698 mm
Wheel base	2760 mm
Kerb weight	1630 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	2
Number of axles	2
Engine number	64283640846285