



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY TCE S/S
Colour	White
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	190 Nm at 2.000 rpm
Engine capacity	1.199 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-10-27
Pictures	54
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-25
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	38
Total items failed	0

MOT #12	2023-10-23 14:50
---------	------------------

MOT test number	881249916484
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-25
------------------	------------

- Advice

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2023-10-23 08:28

**MOT test number**

421230701604

**Result****✗ Failed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

**MOT #10**

2022-10-26 10:15

**MOT test number**

868402361158

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2022-10-26 08:28**MOT test number** 596235183541**Result** ✗ Failed

**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2022-09-10 10:52**MOT test number** 912924728587**Result** ✗ Failed

**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge thin edges (5.2.3 (e))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing inner side wall (5.2.3 (d) (ii))

**Advice** Possible fuel or air induction leak but unable to confirm, strong fumes offside front of engine

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge thin edges (5.2.3 (e))

**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing inner side wall (5.2.3 (d) (ii))

**MOT #7** 2021-10-04 10:59**MOT test number** 421409736518**Result** ✓ Passed**MOT #6** 2020-07-13 13:22**MOT test number** 546859786721**Result** ✓ Passed

**MOT #5** 2019-06-14 15:27**MOT test number** 695831945237**Result** ✓ Passed**MOT #4** 2019-03-12 11:31**MOT test number** 258578122657**Result** ✓ Passed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #3** 2018-03-06 15:07**MOT test number** 376809913433**Result** ✓ Passed**MOT #2** 2017-03-14 10:14**MOT test number** 209295535086**Result** ✓ Passed**Advice** Front Outer Tyre worn close to the legal limit WORN ON OUTSIDE (4.1.E.1)**Advice** Oil leak**MOT #1** 2016-03-30 09:01**MOT test number** 723031895644**Result** ✓ Passed**Advice** Offside rear brake binding slightly (borderline fail)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
25 October 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	25 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-29
Last registration	2023-10-23
Complete history	<a href="#">See info</a>



Registration #1	2013-03-29	20 mi
Registration #2	2016-03-30	19.636 mi
Registration #3	2017-03-14	24.849 mi
Registration #4	2018-03-06	31.641 mi
Registration #5	2019-03-12	40.821 mi
Registration #6	2019-06-14	43.125 mi
Registration #7	2020-07-13	44.697 mi
Registration #8	2020-09-29	45.277 mi
Registration #9	2020-12-01	45.857 mi
Registration #10	2021-02-23	46.437 mi
Registration #11	2021-05-16	47.017 mi
Registration #12	2021-08-08	47.597 mi
Registration #13	2022-10-23	48.177 mi
Registration #14	2023-10-23	48.757 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1808 mm
Height	1471 mm
Length	4295 mm
Wheel base	2641 mm
Kerb weight	1205 kg
Max. allowed weight	1787 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D022899