



report date: 2024-03-28

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Grey
Year of manufacture	2008
Top speed	98 mph
0 - 60 mph	16.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	159 Nm at 2.000 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	120 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-08-08
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-18
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	24
Total items failed	9

MOT #17	2024-04-19 11:22
MOT test number	173700682905
Result	✓ Passed
Next expiry date	2025-04-18
Minor	Offside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #16	2023-05-25 13:53
MOT test number	454414809904
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15	2023-05-23 09:57
MOT test number	996484500894
Result	✗ Failed
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Nearside Rear Tyre has ply or cords exposed cracking in road tread and a screw on the inside edge (5.2.3 (d) (ii))
Fail	Nearside Front Brake pipe excessively corroded (1.1.11 (c))
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #14**

2021-08-27 10:44

MOT test number

214072769509

Result

✓ Passed

- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material marked (1.1.11 (c))

MOT #13

2021-08-26 14:11

MOT test number

379262338405

Result

✗ Failed

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material marked (1.1.11 (c))

MOT #12

2020-09-08 09:38

MOT test number

455246878766

Result

✓ Passed

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Exhaust has a minor leak of exhaust gases center pipe (6.1.2 (a))

**MOT #11** 2019-08-20 13:53**MOT test number** 350010084768**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2019-08-20 11:59**MOT test number** 178453541237**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases back box (6.1.2 (a))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #9** 2018-08-11 11:01**MOT test number** 174904773514**Result** ✓ Passed**MOT #8** 2017-08-21 13:28**MOT test number** 650753783732**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2017-08-21 09:19**MOT test number** 354958974820**Result** ✗ Failed**Advice** Rear Rear fog lamp damaged, but still visible from a reasonable distance lamps full of water (1.3.2d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2016-08-19 09:26**MOT test number** 669199386159**Result** ✓ Passed**MOT #5** 2015-09-09 09:04**MOT test number** 201523173363**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-07-30 10:48**MOT test number** 287321114243**Result** ✓ Passed**MOT #3** 2013-07-16 15:47**MOT test number** 369117693175**Result** ✓ Passed**Notice** Back box corroded**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #2** 2012-07-13 11:47**MOT test number** 796975792151**Result** ✓ Passed**MOT #1** 2011-07-05 15:34**MOT test number** 405586881135**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
18 April 2025

Tax status	Valid until 1 May
Days left	2
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-07-17
Last registration	2024-04-19
Complete history	See info



Registration #1	2008-07-17	6 mi
Registration #2	2011-07-05	34.264 mi
Registration #3	2012-07-13	49.889 mi
Registration #4	2013-07-16	63.799 mi
Registration #5	2014-07-30	72.376 mi
Registration #6	2015-09-09	82.452 mi
Registration #7	2016-08-19	90.874 mi
Registration #8	2017-08-21	98.857 mi
Registration #9	2017-08-21	98.857 mi
Registration #10	2018-08-11	106.031 mi
Registration #11	2019-08-11	113.205 mi
Registration #12	2020-08-11	120.379 mi
Registration #13	2021-08-11	127.553 mi
Registration #14	2022-08-11	134.727 mi
Registration #15	2023-08-11	141.901 mi
Registration #16	2024-04-19	149.075 mi
Registration #17	2024-04-19	156.249 mi
Registration #18	2024-04-19	163.423 mi
Registration #19	2024-04-19	170.597 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

8K84515