



NA57FGP

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX 16V URBAN FOX
Colour	Black
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	124 Nm at 2.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg






Internet history

Entry 1

Date	2021-07-14
Pictures	32
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #14</b>	2021-07-14 10:14
<b>MOT test number</b>	381706427420
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-07-13
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Power steering component has slight seepage from a component pipe (2.1.5 (a))

<b>MOT #13</b>	2020-09-01 08:42
<b>MOT test number</b>	460976717957
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Drive shaft flexible coupling slightly deteriorated (6.1.7 (d) (i))

<b>MOT #12</b>	2019-09-05 07:02
<b>MOT test number</b>	161916716660
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
<b>Advice</b>	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #11** 2019-09-04 12:50**MOT test number** 672487978916**Result** ✗ Failed**Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Exhaust system insecure exhaust sleeve (6.1.2 (a))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #10** 2018-09-06 08:18**MOT test number** 922101423495**Result** ✓ Passed**MOT #9** 2017-09-18 13:36**MOT test number** 556014229200**Result** ✓ Passed**Advice** Nearside Rear brake slight bind**Advice** Rear shockers corroded**MOT #8** 2016-09-19 14:37**MOT test number** 406631659789**Result** ✓ Passed

**MOT #7** 2015-08-28 09:13**MOT test number** 839670545274**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2014-08-29 09:44**MOT test number** 356851744203**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Offside rear tyre perrished**MOT #5** 2013-09-23 10:31**MOT test number** 806286363244**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2013-09-23 09:52**MOT test number** 589086463201**Result** ✗ Failed**Fail** Rear Tyre(s) incorrect because tyres with different aspect ratios are fitted on the same axle.  
(4.1.A.1a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2012-09-07 14:41**MOT test number** 179461852201**Result** ✓ Passed



MOT #2	2011-09-07 10:44
MOT test number	446320251281
Result	✓ Passed

MOT #1	2010-09-03 11:48
MOT test number	103316040251
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>NA57FGP</b>
Plate since	2024-03-29
Current registration	 <b>NA57FGP</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-09-12
Last registration	2021-07-14
Complete history	<a href="#">See info</a>



Registration #1	2007-09-12	25 mi
Registration #2	2010-09-03	25.260 mi
Registration #3	2011-09-07	32.414 mi
Registration #4	2012-09-07	40.322 mi
Registration #5	2013-09-23	45.254 mi
Registration #6	2013-09-23	45.254 mi
Registration #7	2014-08-29	49.722 mi
Registration #8	2015-08-28	54.067 mi
Registration #9	2016-08-28	58.317 mi
Registration #10	2017-08-28	62.567 mi
Registration #11	2018-08-28	66.817 mi
Registration #12	2019-08-28	71.067 mi
Registration #13	2020-08-28	75.317 mi
Registration #14	2021-07-14	79.567 mi
Registration #15	2021-07-14	79.567 mi
Registration #16	2021-07-14	79.567 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1093 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BKR 031365