



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Black
Year of manufacture	2008
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





## MOT history

MOT expiry date	2024-11-15
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	43
Total items failed	7

MOT #18	2023-11-16 11:06
MOT test number	648094018406
Result	✓ Passed
Next expiry date	2024-11-15
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

MOT #17	2023-11-09 13:01
MOT test number	205017653249
Result	✗ Failed
MAJOR	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))
MAJOR	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
MAJOR	Horn not working (7.7 (a))
MAJOR	Exhaust system insecure (6.1.2 (a))

**MOT #16** 2022-11-14 14:57**MOT test number** 463047114200**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2021-11-08 18:10**MOT test number** 208939433939**Result** ✓ Passed**MOT #14** 2020-11-04 09:27**MOT test number** 643185452235**Result** ✓ Passed**Advice** All suspension is deteriorated/corroded**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** N/s headlamp has condensation but not affecting the beam pattern**Advice** Front Brake pad(s) wearing thin all (1.1.13 (a) (ii))**MOT #13** 2019-05-13 09:50**MOT test number** 363749643414**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #12**

2019-05-08 07:54

**MOT test number**

132370693064

**Result****✗ Failed**

**MAJOR** Electrical wiring insecure and in contact with sharp edges Wiring from battery positive fouling in gearchange mech (4.11 (a) (ii))

**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MAJOR** Nearside Rear Suspension arm pin or bush excessively worn Front bush (5.3.4 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #11**

2018-05-12 07:53

**MOT test number**

441866310009

**Result****✓ Passed****MOT #10**

2018-05-10 15:27

**MOT test number**

542598831973

**Result****✗ Failed**

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened Both (3.5.1i)

**Advice** Nearside Front Tyre worn close to the legal limit 2.1mm (4.1.E.1)

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm Tyre is also damaged on outer side wall but no ply or cords are exposed at present (4.1.E.1)

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened Both (3.5.1i)

**MOT #9** 2017-04-06 12:16**MOT test number** 350612717190**Result** ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened Both side brake discs scored and pitted. (3.5.1i)
- Advice** Offside Front Tyre outer side wall has a minor cut.
- Advice** Front registration plate deteriorated but not likely to be misread Number plate damage. (6.3.1d)
- Advice** Rear Exhaust shield insecure.
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened Both side brake discs scored and pitted. (3.5.1i)
- Advice** Rear Both tyres inner shoulder wearing smooth and uneven

**MOT #8** 2016-03-30 13:07**MOT test number** 851464286796**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7** 2016-03-30 12:02**MOT test number** 939184585952**Result** ✗ Failed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Offside Headlamp not working on dipped beam (1.7.5a)

**MOT #6** 2015-03-02 16:13**MOT test number** 906561265068**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-03-02 14:24**MOT test number** 148211065008**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #4** 2014-03-05 15:28**MOT test number** 488414564060**Result** ✓ Passed**Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #3** 2013-02-14 12:20**MOT test number** 439855643025**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2012-03-01 14:58**MOT test number** 399171062077**Result** ✓ Passed**MOT #1** 2011-02-03 09:07**MOT test number** 855534731032**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
15 November 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	15 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>SG08FXS</b>
Plate since	2019-03-28
Current registration	<b>SG08FXS</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-01
Last registration	2023-11-16
Complete history	<a href="#">See info</a>



Registration #1	2008-03-01	11 mi
Registration #2	2011-02-03	38.208 mi
Registration #3	2012-03-01	46.252 mi
Registration #4	2013-02-14	54.937 mi
Registration #5	2014-03-05	63.760 mi
Registration #6	2015-03-02	71.928 mi
Registration #7	2015-03-02	71.928 mi
Registration #8	2016-03-30	82.585 mi
Registration #9	2016-03-30	82.558 mi
Registration #10	2017-04-06	90.334 mi
Registration #11	2018-05-22	95.277 mi
Registration #12	2019-05-22	95.277 mi
Registration #13	2020-05-22	95.277 mi
Registration #14	2021-05-22	95.277 mi
Registration #15	2022-05-22	95.277 mi
Registration #16	2023-05-22	95.277 mi
Registration #17	2024-05-22	95.277 mi
Registration #18	2025-05-22	95.277 mi
Registration #19	2026-05-22	95.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1457 mm
Length	4830 mm
Wheel base	2754 mm
Kerb weight	1590 kg
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	8L50847